

Factor Settings

50


X1:


X2:


X3:

1: Oven Temp


2: Carb Conc 3: Quench Temp









Block Plot












Robustness Factor Setting






Factor

Halfnormal Probability Plot of |Effects|



Halfnormal Distribution Order Statistic Medians



Cumulative Model

