DEVIATION REPORT
Deviation: RM-10001 lot L25-0444
Deviation No.: DEV-2025-012
Revision: 01
Opened: 2025-07-09
Material: RM-10001
Lot: L25-0444
Site: Northfield
Approved by: Priya Hartmann

1. DESCRIPTION
During dispensing of lot L25-0444, operator Owen Moreau (E104284) recorded a weight outside to

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Balance out of calibration.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.