DEVIATION REPORT
Deviation: RM-10004 lot L25-0555
Deviation No.: DEV-2025-015
Revision: 01
Opened: 2025-08-17
Material: RM-10004
Lot: L25-0555
Site: Northfield
Approved by: Hugo Kowal

1. DESCRIPTION
During dispensing of lot L25-0555, operator Sami Quiroga (E104305) recorded a weight outside t

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Transcription error.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.