

INCIDENT REPORT - FLANGE LEAK AT E-101 INLET

Incident No: INC-2026-0092 Date: 29 Jul 2026 Severity: minor (no injury)

WHAT HAPPENED

Hydrocarbon weep observed at the E-101 shell inlet flange during a routine round. Estimated release under 2 litres; area barricaded and the flange hot-bolted.

CAUSE

Gasket relaxation after a thermal cycle; bolt torque found 20% below specification.

ACTIONS

Replace the gasket at the turnaround; add E-101 inlet flange to the torque audit list. Link to inspection report IR-2026-0147 for shell condition.