INSPECTION REPORT

Damaged Concrete Pipe Culvert (Ø 24”)

Location: Brgy. Avancena, Koronadal City
Date Inspected: January 19, 2026

Findings:
The existing 24-inch concrete pipe culvert is damaged and partially collapsed, causing open holes and uneven road surface. The condition is dangerous for drivers and may cause vehicular accidents.

Recommendation:
Immediate replacement of the damaged culvert is recommended to prevent accidents and further road deterioration.

Engr. Severino Johnrome E. Usero

GPS Map
Camera Lite
GVR9+CQ9, Koronadal, South Cotabato, Philippines
Latitude
6.540416666666665°
Longitude
124.86951833333333°
Local 07:44:50 AM
GMT 11:44:50 PM
Altitude 42 meters
Monday, 19.01.2026

GPS Map
Camera Lite
Avanceña, GVR9+CQ9, Koronadal, South Cotabato, Philippines
Latitude
6.540426666666667°
Longitude
124.86956°
Local 07:45:13 AM
GMT 11:45:13 PM
Altitude 41 meters
Monday, 19.01.2026

GPS Map
Camera Lite
GVR9+CQ9, Koronadal, South Cotabato, Philippines
Latitude
6.540495°
Longitude
124.86948499999998°
Local 07:45:45 AM
GMT 11:45:45 PM
Altitude 40 meters
Monday, 19.01.2026

GPS Map
Camera Lite
Lutayan Rd, Koronadal, South Cotabato, Philippines
Latitude
6.5386000000000001°
Longitude
124.86814666666666°
Local 07:49:19 AM
GMT 11:49:19 PM
Altitude 41 meters
Monday, 19.01.2026

GPS Map
Camera Lite
Lutayan Rd, Koronadal, South Cotabato, Philippines
Latitude
6.538475°
Longitude
124.86772166666667°
Local 07:49:25 AM
GMT 11:49:25 PM
Altitude 42 meters
Monday, 19.01.2026


GPS Map
Camera Lite
Lutayan Rd, Koronadal, South Cotabato, Philippines
Latitude
6.5385083333333345°
Longitude
124.867695°
Local 07:49:45 AM
GMT 11:49:45 PM
Altitude 41 meters
Monday, 19.01.2026