INSPECTION REPORT

Project: Concrete Enclosure of Window Opening
Building: Radiology Building, City Health Office
Location: Koronadal City

Purpose of Inspection:
To assess the existing window opening at the Radiology Building and determine the necessary corrective measures to improve safety, security, and radiation protection.

Observation:

Item	Description
Existing Opening	Aluminum sliding window with glass panels
Opening Size	1.20 m (L) × 0.25 m (W) × 0.5 m (H)
Location	Radiology Room
Condition	Window opening exposes interior to security and safety risks
Risk Identified	Unauthorized access, inadequate radiation containment

Findings:

1. The existing window opening is inappropriate for a radiology facility**.**
2. Glass panels do not provide adequate protection against intrusion.
3. The opening may compromise radiation shielding requirements.

Recommendation:
It is recommended to permanently enclose the existing window opening to improve safety, security, and radiation protection.

Inspected by: Engr. Severino Johnrome E. Usero
Date of Inspection: 15 January 2026

H= 0.5 meters
W = 0.25 meters
L= 1.2 meters
GPS Map Camera Lite
FVG7+JPX, Koronadal, South Cotabato, Philippines
Latitude
6.4946663°
Longitude
124.8378923°
Local 02:30:18 PM
GMT 06:30:18 AM
Altitude 70 meters
Thursday, 15.01.2026