GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	:	1 of 2	Revision	:	00/10/05	
1 0	0			Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Screw Conveyor						

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Screw Conveyor in the repack facility

Procedure: *The proper process to lockout the Screw Conveyor is as follows:*

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Turn electrical disconnect off and install pad lock-multi locking device with id tag
- 3. ID tag must contain name, date and time lock out occurs.
- 4. Test the machine to ensure that it is locked out and will not start.

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove Id tag with name, date and time
- 4. Remove padlock-multi locking device
- 5. Place disconnect in the on position
- 6. Test to ensure that machinery is operating properly and available to be placed back in service.

GILES CHEMICAL CORPORATION						
COMPANY PROCEDURE						
Standard Operating Procedure	Page		2 of 2	Revision	:	
Standard Operating Procedure	1 agc	. 2012		Date	:	02/12/07
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Screw Conveyor					

TRAINING DOCUMENTATION

EMPLOYEE	TITLE	SIGNATURE	DATE
1	***************************************		
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			