## Special Customer Requirement

(Production and Shipping requirements)

**#402** 

## **Customer(s):**

## "SCREENED" - Tech Grade Customers

"SM" means all salt is screened to assure all crystals are smaller than 20 mesh and larger than 60 mesh

## MIDDLE CUT ONLY! - NO "OVERS" OR "FINES"

Usually for customers needing specific bulk density and / or sensitive to dust

ct: C10T22	00-SM				
Tech Grade		] - USP Grade	🗌 - Liqu	ıid	
Screened 20/6	0	] - Screened 60	Oth	er	
		(screen out dust)			
		Use o	ne small zin loc	k hag ner sample	
- Take Samples -		Use time clock on bag before taking samples.			
		One sampl	le from screened	l salt chute every hor	ur.
0 0	:				
				Must be centered on pallet	
Type of Sacks - Sten		cil sacks 2,200 lb stencil		Weight per Sack	2,200-lbs
Liners Required -		- Bottom Tie	☐ - Bottom Tie Grommets ☐ - Use Blace		c Cable/Zip Ties
- Placards Required -		Staple a Placard to each sack		"SCREENED MATERIAL"	
				''2,200-lbs'' '' Sack Initials ''	
_ Other Require	ments -			Sack	Initials
Outer requires					
ng:					
✓ General - Load according to Giles loading chart and quantity on Bill of Lading					
- Air Bags - Double Wrap - Corner Boards -					
Must have Qua	ality Approva	l before loading	Must have	Management Appro	val before loading
✓ Other I	etter of correc	et load will be indic:	ated on the Pick	slin by Quality Den	artment
Must load Quality designated load and must load correct amount.					
n History:					
Date Change					
05/10/06	Replaced SCR - 41 & 42				
04/05/07 Changed Product code and moved from 2,000 to 2,200 lbs					
	☐ - Tech Grade ☐ - Screened 20/60 ☐ - Take Samples  tion / Packaging Type of Film - Number of Bags pe Type of Sacks - ☐ - Liners Require ☐ - Other Require ☐ - Other Require ☐ - Air Bags ☐ - Must have Quade	<ul> <li></li></ul>	□ - Tech Grade □ - USP Grade □ - Screened 20/60 □ - Screened 60 (screen out dust)  Use of Use time One sample of Film - Number of Bags per pallet	Tech Grade	Tech Grade