


4.2 Types of binary phase diagrams

Simplest type: Binary isomorphous phase diagrams

➤ Formation of microstructures in isomorphous alloys



Applies to slow cooling! (equilibrium)

Ni and Cu atoms must diffuse during cooling in order to reach the **equilibrium concentration**

(otherwise: **formation of segregated solid solutions!**)