Engineering report

Water damage / Claim C-1042

DOCUMENT VERSION D-03-v1

DOCUMENT CONTENTS

Inspection record 02

Opinion and recommendation 03

Inspection record

I recorded the inspection on 12 May. I examined the kitchen ceiling and the utility room above it.

Opinion and recommendation

Opinion

A leak at the utility-room supply coupling is one possible explanation for the pattern of moisture. My visual inspection did not establish the source of the water.

Recommendation

I recommend a pressure test of the supply pipe and connection to help distinguish this possibility from another route of water entry.