## **Prerequisites to Operate the Machine:**

## SE SE COMPANS

## 1) Electrical Power Requirements:

✓ Voltage : 400 / 440 VAC

✓ Load:

Stir Casting Machine (2 Kg) : 9.5 KW

■ Frequency : 50 / 60 Hz

Phase : 3 Phase with Neutral & Earth Connection

For Optional Attachments

Vacuum Die Casting : 2 KW	Squeeze Die Casting: 5 KW	Rotary Centrifugal Casting: 3 KW
Rotary Centrifugal Casting: 3 KW	Powder Vibrator : 2 KW	Ultrasonic Vibrator : 4 KW

- ✓ Electrical wire connection should be terminated with 32 Amps, 4 Pole MCB
- ✓ 4 Sq.mm or 6 Sq.mm wire should be used for all input phases and for neutral.

## 2) Others:

- ✓ For Squeeze Die Casting Attachment (Optional)
  - O A pit (Cemented) needs to be constructed for Squeeze casting setup at the installation site.
  - HYRO 68 Grade Hydraulic Oil (Make: Servo), 80 liters must be provided by you
- ✓ For Ultrasonic Vibrator Attachment (Optional)
  - o Running Water (TAP Water) inlet & drain connection is required to cool the ultrasonic horn.