Official Incident Report

Initial Incident Details			
Incident Raised By:	SMART (Mr. Chhun Pao)	**Incident Received By:**	Mr. VIN Rithea
Reported Date:	15-Sep-2026	**Service Disruption:**	IX1222

Detailed Incident Information			
Incident date:	15-Sep-2026	**Report Time:**	21:23
Incident Number:	TCT#1970595	**Incident Category:**	SLA
Customers Impacted:	SMART	**Duration of Interruption**	00hrs 00mins

Incident Description / Root Cause Analysis			
Incident Number	**Report Time**	**Restored Time**	**Duration**
TCT#1970595	15-Sep-2026 21:23	15-Sep-2026 19:45	00hrs 00mins

Root Cause Analysis – Chronology of Events

Details of Incident

Incident Number:	TCT#1970595
Date and Time:	15-Sep-2026 (UTC+7)
Time of Complaint:	15-Sep-2026 21:23
Issue Reported:	SMART reported a connection issue with CID: IX1222, which was identified as traffic degradation.

Actions Taken: Acknowledgment, Investigation, Resolution & Root Cause Analysis

Date and Time: 15-Sep-2026

19:00 TELCOTECH detected degradation in international traffic and began investigating the issue and escalating it.
19:09 TELCOTECH escalated the issue to the partner for further investigation and resolution.
19:19 The partner acknowledged the issue.
19:45 TELCOTECH detected that traffic had returned to normal.
21:23 TELCOTECH received a customer complaint via the Telegram group regarding the traffic degradation that occurred from 19:00 to 19:45.
23:39 TELCOTECH followed up with the partner to request the RFO.

Date and Time: 16-Sep-2026

08:41 TELCOTECH followed up with the partner again to request the RFO.
10:03 The partner advised that one of its upstream providers had experienced an issue, causing traffic along this path to degrade. The upstream provider carried out restoration work.

Fault Analysis & Resolution	
Cause of Outage:	The upstream international connection experienced quality degradation due to a double fault at one of the upstream providers, resulting in degraded traffic through this path.
Fault GPS Location:	Muang Phin, Lao.
Resolution:	The service was restored by the upstream provider after repairing the faulty cables.
Permanent Fixed:	Yes

Picture Reference

