Wholesale Products & Service Delivery

Incident Report

Initial Incident Details			
Incident Raised By:	SMART (Mr. Chhun Pao)	**Incident Received By:**	Mr. HOUT Heang
Reported Date:	11-Sep-2026	**Service Disruption:**	IX1222

Detailed Incident Information			
Incident date:	11-Sep-2026	**Report Time:**	16:37
Incident Number:	TCT#1968379	**Incident Category:**	SLA
Customers Impacted:	SMART	**Duration of Interruption**	03hrs 28mins

Incident Description / Root Cause Analysis					
Incident Number	**Time Issue**	**Raise Time**	**Response Time (WHSS)**	**Restored Time**	**Duration**
TCT#1968379	11-Sep-2026 13:00	11-Sep-2026 13:35	11-Sep-2026 13:36	11-Sep-2026 17:03	03hrs 28mins

Root Cause Analysis – Chronology of Events

Details of Incident

Incident Number:	TCT#1968379
Date and Time:	11th-Sep 2026 (Cambodia local time, GMT+7)
Time of Complaint:	11th-Sep-2026 13:00
Issue Reported:	SMART reported a connection issue with CID: IX1222, which was identified as traffic degradation.

Actions Taken: Acknowledgment, Investigation, Resolution & Root Cause Analysis

Date and Time: 11-Sep-2026

13:00 TELCOTECH detected degradation in international traffic and began investigation and escalation.

13:16 The issue was escalated to the partner for further investigation and resolution.

13:35 TELCOTECH received a customer complaint regarding the traffic degradation via the Telegram group.

13:36 TELCOTECH followed up with the partner again.

13:52 Partner acknowledged the issue and assigned a trouble ticket for further investigation.

14:03 TELCOTECH followed up with the partner for the latest status and restoration progress.

14:36 Partner advised that their upstream provider had identified a cable fault in Malaysia and that restoration work had been prioritized.

15:01 Partner provided an estimated restoration time of approximately 2 hours.

15:37 TELCOTECH escalated the issue to the partner's escalation team and requested further action to expedite restoration with their upstream provider.

17:05 Partner requested TELCOTECH to recheck the status of the affected circuit.

17:27 Partner confirmed that the issue had been permanently fixed by their upstream provider.

17:45 TELCOTECH rechecked the service and confirmed that traffic had resumed and service performance had returned to normal.

Fault Analysis & Resolution	
Cause of Outage:	The upstream international connection experienced quality degradation caused by a cable fault in the Malaysia segment.
Fault GPS Location:	Malaysia segment.
Resolution:	The partner coordinated with upstream providers to balance the load and redirect customer traffic to other routes.
Permanent Fixed:	Yes