Equations

$$H_c l_c = Ni_{coil}$$

$$B_c = \mu H_c$$
$$\mu = \mu_0 \mu_R$$

$$\mu_0 = 4\pi \times 10^{-7} \frac{\mathrm{H}}{\mathrm{m}}$$

Permeability of free air