

The peak current of the motor is 9.5A and the peak phase current of the driver is 8A. The motor have 3 phases and at least two of them active at once. This means that the approximate minimum peak phase current needed for efficient control is:

