


DB-D3100-V3.1


Page	Title
01	COVER & SYS DIAGRAM
02	D3100
03	TYPE C_AV_IN_USB
04	LCD_BT_AUDIO
05	POWER
06	MS9601A_SENSE

Date	Update History	BY
2023-6-8	Create the first version.	Hank
2023-10-15	Fix power supply issue	Hank




TYPE C

[2,6]	I2C1_SCL	I2C1_SCL
[2,6]	I2C1_SDA	I2C1_SDA
[4]	BOOST_EN	BOOST_EN
[4]	PWR_EN	PWR_EN



USB/1


[2]	USB0PP	USB0PP
[2]	USB0PN	USB0PN
[2]	USB1PP	USB1PP
[2]	USB1PN	USB1PN
[4]	WIFI_ENJ	WIFI_ENJ



AV IN

CVBS_IN

[2]	CVBS_IN	CVBS_IN
[4]	AUDIN_INL	AUDIN_INL
[4]	AUDIN_INR	AUDIN_INR
[4]	AUX_DET	AUX_DET



Zhuhai Hi-Chip Technology Co., Ltd.

Size
B

Document Number





03_TYPE C_AV_IN_USB

Rev
V3.1

Date: Monday, March 11, 2024

Sheet 3 of 6


[2] LVDS-DN[0..7] <<< LVDS-DN[0..7]
 [2] LVDS-DP[0..7] <<< LVDS-DP[0..7]
 [2] LVDS-CN[0:1] <<< LVDS-CN[0:1]
 [2] LVDS-CP[0:1] <<< LVDS-CP[0:1]
 [2] LCD_CS <<< LCD_CS
 [2] LCD_SCL <<< LCD_SCL
 [2] LCD_SDA <<< LCD_SDA

[illegible]


[2]	SPDIF	SPDIF
[3]	AUDIN_INR	AUDIN_INR
[3]	AUDIN_INL	AUDIN_INL
[3]	AUX_DET	AUX_DET
[2]	UART2_TX	UART2_TX
[2]	UART2_RX	UART2_RX
[5]	ADKEY	ADKEY
[5]	BT_IRRX	BT_IRRX
[5]	BL_EN	BL_EN
[5]	VBIAS_EN	VBIAS_EN
[5]	PWR_EN	PWR_EN
[5]	WIFI_ENU	WIFI_ENU
[2]	XP_CRSTJ	XP_CRSTJ
[2]	24M_OUT	24M_OUT
[2]	IRRX	IRRX
[3]	BOOST_EN	BOOST_EN

[illegible][illegible]


VDDCORE 1.2V




VDDO 1.5V





VDD33 3.3V




BACKLIGHT



LCD VBIAS



IR SENS




ADC KEY

[4] ADKEY << ADKEY

IRRXX

[4] BT_IRRX << BT_IRRX

DC5V



Zhuhai Hi-Chip Technology Co.,Ltd.

Size B

Document Number

05_POWER

Rev V3.1

Date: Monday, March 11, 2024

Sheet 5 of 6

