

Port	Funktion
0	Output PU ? Temperatursensor
1	
2	Analog Input Batteriespannung
3	
4	Output PU XLC-6 1
5	SPI SS
6	
7	
8	
9	
10	
11	Output PU Licht Rück F
12	Output PU Licht Rück R
13	Output PU Licht Front R
14	
15	Output PU XLC-6 2
16	
17	SPI CL
18	SPI MISO
19	
20	I2C SDA
21	I2C SCL
22	SPI MOSI
23	
24	Output AN 4QD POT
25	Output PU 4QD ON
26	Output PU Licht Rück F
27	
28	
29	
30	
31	
32	Output PU Horn
33	Output PU 4QD DIR
34	
35	Input Hallsensor

Loksteuergeraet

