





Burn mark associated with overheating along the metallic interconnection (without back-sheet damage) [Köntges14].

f e m

2 3



Front and back side view of burn marks caused by open-circuited bypass diodes and current mismatch conditions (due to shading or cracked cells) [Köntges14].

f e m

3 4 5