






Detached junction box from backsheet [By the courtesy of SUPSI PVLab].



Burned junction box caused by corroded contacts within the junction box [By the courtesy of TUV Rheinland].



Overheating due to the poor Jbox interconnect leading to burn mark and glass breakage [Yang19].



IR imaging of a hotspot Jbox due to loose electric connection inside [Yang19].

