




Improper installation of clamp [By courtesy of SUPSI PVLab].

Glass breakage caused by poor clamp design [Moser17]. (see also PVFS 1-8)

Undersized mounting structure for local snow load conditions [Köntges16].

Undersized mounting structure for local wind conditions [India13].

