

Incident Report - INC-4026

Type: Electric Fault

Location: Zone C

Date: 2025-05-10

Severity: Low

Description:

At approximately 00:57:04 on 2025-05-10, an electrical fault was reported in Zone C, causing partial power outage in nearby buildings. Witnesses noted sparks and a burning smell from a junction box near the sidewalk. Power disruption impacted residential flats and street lighting in the area, and the incident was escalated to city maintenance.

Action Taken:

The electrical maintenance crew responded quickly and isolated the faulty node. Temporary power was restored via an alternate supply loop. The burnt components were replaced, and safety inspections were conducted on adjacent infrastructure. Root cause analysis indicated water seepage. Insulation upgrades have been initiated.