

Regular Visual Termite Inspection Report in accordance with AS 3660.2-2017**H 1120337**

Client: Cardow + Partners. Re: Structure at: WO # 58139-1980

Address: 31 Arkan AVE
Woolgoolga State: NSW Postcode:

Phone: 6654 1148 Fax: Mobile:

Date of the Inspection: 24/7/26 Invoice No:

1. Brief description of the building and other structures on the property:

Type: Domestic ☒ Commercial ☐ Apartment/Unit/Flat ☐ Other:

Height: Single Storey ☒ Multistorey ☐ Split Level ☐ Other:

Building: Cavity Brick ☐ Brick Veneer ☒ Concrete Block ☐ Stone ☐ Weather-board ☐ Stucco ☐ Plastic/Vinyl ☐
Aluminium ☐ Hardiplank ☐ Coated Metal Sheetting ☐ Other Sheetting ☐ Other:

Piers: Brick ☐ Concrete ☐ Timber ☐ Stone ☐ Steel ☐ Other:

Floor: Concrete Slab ☒ Timber with Concrete Areas ☐ Timber ☐ Chipboard ☐ Infill Slab ☐
Timber with hardboard areas ☐ Other:

Roof: Tile ☒ Coated Metal ☐ Iron ☐ Aluminium ☐ Other:

Fences: Colour Bond Type ☒ Timber ☐ Brick ☐ Wire & Post ☐ Other:

1.1 Brief description of areas inspected:

Interior ☒ Roof void ☒ Subfloor ☐ Wall exterior ☒ Garage ☒ Carport ☐ Out buildings ☐ Trees ☒ Stumps ☒
Posts ☐ Fences ☒ Garden ☒ Timber retaining walls ☐ Landscaping timbers ☐ Other:

Only structures, fences, trees etc within 50 m of the building but within the boundary of the property were inspected. When a building, or part of a building is constructed on a concrete slab it is always more susceptible to concealed termite entry.

1.2 Area/s* NOT Inspected and/or Area/s* to which REASONABLE ACCESS for Inspection was NOT AVAILABLE and the Reason/s why:

☐ Interior because

☒ Roof void because Reasonable access was not available.

☐ Subfloor because

☐ Wall exterior because

☐ Garage because

☐ Carport because

☐ Out buildings because

☐ Trees, stumps and/or posts because

☐ Fences because

☐ Garden and landscaping timbers because

☐ Timber retaining walls because

☒ Slab edge, which normally would be exposed because Covered by Garden.

☐ Other: because

* Since a complete inspection of the above areas was not possible, termite activity and/or damage may exist in these areas.

No inspection was made, and no report is submitted, of inaccessible areas. These include, but may not be limited to, concealed frame timbers, eaves, areas concealed by concrete floors, wall linings, soil, landscaping, rubbish, floor coverings, furniture, pictures, appliances, stored items, insulation, hollow blocks/posts. Furnishings, furniture & stored items were not inspected.

Client Copy

H 1120337

1.3 High Risk Area(s) to which Access should be gained, or fully gained, since they may show evidence of termites or damage:

Interior ☐ Roof void ☐ Subfloor ☐ Wall exterior ☐ Garage ☐ Carport ☐ Out buildings ☐ Slab Edge ☐ Weepholes ☐
Other: _____ Comment: _____

Recommendation: Further Inspections are strongly recommended to areas where Reasonable Access is Unavailable, Obstructed or Restricted or a High Risk of possible Timber Pests and/or Damage exists.

1.4 Was Insulation present in the Roof Void? YES ☒ NO ☐ Unable to determine ☐ Reason: _____

Where insulation is present in the roof void it is recommended it be moved or removed and an inspection be carried out to the wall top plate timbers and other roofing timbers covered by the insulation. This invasive inspection will not be performed unless a separate contract is entered into.

1.5 Was the property furnished at the time of inspection? YES ☒ NO ☐ Comments: _____

Where a property is furnished at the time of the inspection then you must understand that the furnishings and stored goods may be concealing evidence of termite activity. This evidence may only be revealed when the furnishings and stored goods are moved. In this case a further inspection of the property is strongly recommended.

2.0 SUBTERRANEAN TERMITES

2.1 At the time of the inspection were active termites (live insects) found? YES ☐ NO ☒ (if answer is NO go to 2.2)

Active termites were located in but not necessarily limited to the following areas:

Interior ☐ Roof void ☐ Subfloor ☐ Wall exterior ☐ Garage ☐ Carport ☐ Out buildings ☐ Trees ☐ Stumps ☐

Posts ☐ Fences ☐ Garden ☐ Timber retaining walls ☐ Landscaping timbers ☐ Other: _____

The termites are believed to be: *Coptotermes species* ☐ *Schedorhinotermes species* ☐ *Nasutitermes species* ☐

Heterotermes species ☐ *Mastotermes darwiniensis* ☐ *Microcerotermes species* ☐ Other: _____

and have the potential to cause Moderate ☐ Moderate to Extensive ☐ Extensive to Severe ☐ amounts of damage to timber including structural damage.

2.2 A termite nest was found - NO ☒ YES ☐ (state the location): _____

Where a termite nest is located on or near the property, the risk of termite infestation is increased.

2.3 At the time of the inspection was visible evidence of subterranean termite workings and/or damage located? YES ☐ NO ☒

If no evidence of termites was found at this inspection be aware that at the initial stages of a termite attack there is often no evidence that an attack has commenced, such evidence may only become apparent sometime after the attack has commenced. As the Inspection can only report details of what was found on the day of the inspection, we strongly recommend that should you find evidence of new termite workings or damage prior to the next recommended Inspection you should contact our Company immediately.

2.4 Termite damage ☐ and/or workings ☐ were found mainly in but not necessarily limited to:

Interior ☐ Roof void ☐ Subfloor ☐ Wall exterior ☐ Garage ☐ Carport ☐ Out buildings ☐ Trees ☐ Stumps ☐

Posts ☐ Fences ☐ Garden ☐ Timber retaining walls ☐ Landscaping timbers ☐ Other: _____

Comments: No Evidence found.

VERY IMPORTANT: Where any termite activity or damage is noted you must realise that further termite damage may be present in concealed areas. A building expert should determine the full extent of damage See Clauses 3, 4 and 5 on page 1.

Whilst we are not builders, the termite damage appears to be:- Moderate ☐ Moderate to extensive ☒ Extensive ☐

Extensive & Severe ☐ See Clause 4 on page 1. More information on general areas of damage and/or activity may be given on page 8 at Additional Information and/or Mud Map.

IMPORTANT: If no live termites were noted above but visual evidence of termite workings and/or damage or any other signs of termites are reported then there may be active termites in concealed areas. Termites may still be active in the immediate Vicinity and may return to cause further damage. In most cases it may not be possible without the benefit of further investigation and subsequent inspections to ascertain whether an infestation is active or inactive. Active termites may simply have not been present at the time of inspection due to a prior disturbance, climatic conditions, or they may have been utilising an alternative feeding source. Continued, **regular, inspections are essential.** Unless written evidence of an appropriate termite management program in accord with "AS 3660 Termite Management" is provided, a treatment must always be considered to reduce the risk of further attack.

2.5 High Moisture Readings: Were found? YES ☒ NO ☐ if yes, the areas were: SHOWER BASE/WALL

If high moisture readings are found and unaccounted for, the use of a Termite Movement Tracker, Thermal Imaging Camera or a Termite Detection Animal if practical or determined necessary by the inspector, may provide further supportive evidence but If high moisture was reported then you must have a building expert investigate the moisture and its cause and determine the full extent of damage and the estimated cost of repairs.

2.6 Was evidence of a possible previous treatment found? ☒ YES ☐ NO If Yes Describe: _____

2.7 A durable sign was ☒ was not ☐ located. If located, the sign was found in the meter box ☒ the entry to the subfloor ☐ or other _____.

It indicates that a physical ☐ or a chemical treated zone ☐ or Monitoring and Baiting system ☐ or another management system. Describe: chemical soil treatment ☒ has been installed.

If the chemical used was identified its period of protection as provided by the label is _____ years from the date of installation.

The termite management system: Appears to have been maintained ☐. Does not appear maintained ☒. Could not be determined ☐.

Comment: Date Applied 28.9.99.

This firm can give no assurances with regard to work that may have been previously performed by other firms.

2.8 Subterranean termite treatment recommendation: A suitable management program that accords with AS 3660 against subterranean termites is considered Essential ☒. Is recommended ☐. A treatment installed by our firm is current ☐. A recommended treatment as agreed is being installed ☐. Recommended as no treatment is installed ☐. Recommended as installed treatment not verified ☐.

Comment: Annual inspection recommended

2.9 Termite Shields "Ant Caps" form part of Physical Termite Systems. They need to be in good order, complete, continuous and observable in order to fulfil their intended purpose. The function of this type of system is to force termite workings to be exposed if termites are entering or attempting to enter the property. Where it is observed that these conditions are not present, termite shielding must be reported as inadequate.

Client Copy

Whilst not a builder it appears that termite shields are:

Adequate ☐ Inadequate ☐ Not Applicable ☒ Unable to assess ☐

H 1120337

If considered inadequate a builder or other building expert should be consulted.

NB Physical barrier systems installed in wall cavities etc are not visible to inspection and no comment is made on such systems.

2.11 Wood rot: At the time of the inspection was visible evidence of wood decay fungi (rot) found? YES ☒ NO ☐

Evidence was found in Interior ☐ Roof void ☐ Subfloor ☐ Wall exterior ☐ Garage ☐ Fences ☐ Other: Carlin

stump

Wood decay fungi are conducive to subterranean termites. You should consult a builder or other building expert to find out what must be carried out to prevent further decay (repairing of drainage, leaks and/or sealing the timber) and to repair the damage.

2.12 Construction features and/or situations that appear conducive to (may attract) subterranean termite infestation and recommendations are: -

Timber in the subfloor ☐ [remove] Timber stored against the building/s ☐ [remove] Timber debris around the outside of the building/s ☐ [remove] Formwork left in place in subfloor and/or under suspended slabs ☐ [remove] Hot water tank overflow pipe needs to be drained further away from the house or to a drain ☒ [rectify] Trees, stumps and/or timber posts should be test drilled and monitored ☐ [see attached proposal if attached] Timber retaining wall/s should be replaced with non-susceptible materials ☐ [remove & replace, consult a builder first] Landscape timbers should be replaced with non-susceptible material ☐ [remove and replace] Heavy foliage against the building/s ☒ [remove] Timber structures in contact with the soil and are attached to the building/s ☐ [either remove or fit termite proof stirrups between soil and the timber] Patios and paths etc attached to the building/s ☐ [where possible gain access/have regular termite inspections]

Other: -

NOTE: Where timber is used for external structures e.g. Balconies, Verandas it may be susceptible to fungal decay or termite attack, it is recommended that you consult a Builder or other specialist in the field to inspect exposed timbers and provide expert advice on their durability and suitability for the situation in which they are used.

3.0 ENVIRONMENTAL CONDITIONS THAT ARE CONDUCTIVE TO TERMITES

3.1 Drainage: Poor drainage, especially in or into the subfloor or against the external walls, increases the likelihood of termite attack.

Whilst not a plumber, it appears that drainage is generally: Adequate ☐ Inadequate ☒ Not able to assess ☐ Not applicable ☐

Areas where drainage was inadequate or not able to be assessed on the day of inspection it is recommended to consult a plumber/drainier:

Left side of house from Road very wet, Drainage issue?

3.2 Water leaks: Water leaks, especially in or into the subfloor or against the external walls, increases the likelihood of termite attack.

Leaking showers units, leaks from outdoor taps, rainwater tanks or leaks from other 'wet areas' also increase the likelihood of termite attack. Whilst not a plumber, it appears that water leaks are: Present ☐ Not present ☒

Areas where leaks should be attended to by a plumber or other expert and why: Drainage issue, recommend review by plumber.

3.3 Hot Water Services and air conditioning units: which release water alongside or near to building walls need to be connected to a drain as the resulting wet area is highly conducive to termites. If this is not possible the water needs to be piped several meters away from the building.

Is there a need for this work to be carried out? Yes ☒ No ☐

Where drainage is considered inadequate or water leaks are reported then a plumber, builder or other building expert should be consulted.

3.4 Ventilation: Ventilation, particularly to the sub-floor region is important in minimising the opportunity for termites to establish themselves within a property. Whilst not a builder the ventilation appears to be generally: Adequate ☒ Inadequate ☐ Not able to assess ☐ Not applicable ☐

Where ventilation needs to be improved or could not be assessed consult a builder or other expert.

We have attached a proposal to carry out ventilation improvement work: Yes ☐ No ☐ Not applicable ☒

3.5 Slab Edge Exposure: Where external concrete slab edges are not exposed there is a high risk of concealed termite entry. In some buildings built since July 1995 the edge of the slab forms part of the termite shield system. In these buildings an inspection zone of at least 75mm should be maintained to permit detection of termite entry. The edge should not be concealed by render, tiles, cladding, flashing, adjoining structures, paving, soil, turf or landscaping etc. Where this is the case you should arrange to have the slab edge exposed for inspection. Concealed termite entry may already be taking place but could not be detected at the time of the inspection. This may have resulted in concealed timber damage.

Does the slab edge inspection zone fully comply?

No, arrange for slab edge to be exposed ☒ No, not required as it is an infill slab ☐ Not applicable ☐ Yes ☐

Not able to comment - refer to note top of page 6 ☐

3.6 Weep holes in external walls: It is very important that soil, lawn, concrete paths or pavers do not cover the weep holes. Sometimes they have been covered during the rendering of the brick work. They should be clean and free flowing. Covering the weep holes in part or in whole may allow undetected termite entry.

Were the weep holes clear allowing the free flow of air? No, arrange for weep holes to be exposed ☒ Not applicable ☐ Yes ☐
Not able to comment ☐ because _____

3.7 Environmental, other Conditions and/or general information: water issue to left side of property.

3.8 At the time of the inspection the degree of risk of subterranean termite infestation to the overall property was considered to be: Moderate ☐ Moderate to High ☒ High ☐ Extremely High ☐

It is strongly recommended that a full Inspection and Report be carried out every 12 months. Regular inspections DO NOT stop termite attack, but are designed to limit the amount of damage that may occur by detecting problems early.

AS 3660 and AS 4349.3 both recommend at least 12 monthly inspections but strongly advise more frequent inspections. Regular inspections DO NOT stop termite attack, but are designed to limit the amount of damage that may occur by detecting problems early.

ADDITIONAL INFORMATION AND/OR MUD MAP (NOT TO SCALE)
Important: If you become aware of any termite activity DO NOT disturb or treat the termites or their workings in anyway but contact our Company immediately. Home treatments do not work and will invalidate any warranty in place.
Additional Information: _____

MUD MAP KEY

A = Termite Activity (Live)

TM = Termite Workings

D = Damage

P = Possible Damage


/// = Evidence of a previous Treatment

W = Wood Rot

North is



STump - W



The Inspection and Report was carried out by: Cristian O'Brien
(Name of Inspector)

State Licence No: 5103825

Dated this 24th day of July 2026

SIGNED FOR AND ON BEHALF OF: Coff Coast Pest Control
(Name of Company)

Signature: [Signature]