SYNTHETIC DOCUMENT - generated for demonstration only. Not a real policy, claim or person.

Garage Inspection Report

Garage	Sri Lakshmi Auto Works (synthetic garage)
Report no.	GR-0457
Inspection date	4 October 2026
Vehicle	Maruti Suzuki Swift VXi hatchback, silver, 2024 (synthetic record)
Registration no.	KA 01 AB 0000 (synthetic)
Policy number	SYN-MOT-2026-000123

Findings

1. REAR: rear bumper cover cracked and pushed inwards, boot lid creased, left tail lamp cracked. Paint transfer of a dark colour on the rear bumper. The damage is consistent with a strike from behind (see rear photograph).

2. FRONT: front bumper, bonnet, radiator grille and left headlamp damaged. White paint transfer on the front bumper, consistent with contact with a white vehicle.

3. The rear damage appears older in sequence than the front damage: the front bumper bears fresh contact marks that overlie the bonnet latch area, and the rear bumper deformation is deeper than the front.

Assessment

The combined pattern is consistent with a two-impact chain collision: the car was struck from behind and pushed forward into the vehicle ahead, which caused the front damage. The owner told the garage that he only described the rear strike in his first statement and had not mentioned being pushed forward into the white sedan.

The repair estimate EST-0457 covers the FRONT damage only. A separate estimate for the rear damage has not yet been prepared.

Inspected by: S. Mechanic (synthetic person).