

Release Notes for AT32F415 Firmware Library Drivers

V2.0.7-2025/11/24

1. GPIO
 - Updated the function “gpio_bits_toggle()” to optimize operation procedure
2. Updated some notes

V2.0.6-2025/08/04

3. GPIO
 - Added “gpio_bits_toggle()” as a new function.
4. TMR
 - Updated tmr_pwm_input_config(), tmr_encoder_mode_config() and tmr_output_channel_config() to make sure that channels are disabled before channel mode configuration.
5. USART
 - Updated usart_flag_clear() to clear the USART_RDBF_FLAG by reading DT register.
6. Updated some notes.

V2.0.5-2024/12/13

1. Updated CAN driver.
2. Updated USB driver.
3. Updated some notes.

V2.0.4-2024/08/08

1. Updated “i2c_flag_clear” and “i2c_init” function.
2. Updated some notes.

V2.0.3-2024/01/05

1. Fixed the IAR7.4 compilation warning issue of some drivers.
2. Updated the corresponding ERTC interrupt function names in iar/gcc startup file.

V2.0.2-2023/10/26

1. Added the function interrupt_flag_get to each of the IP sections

2. Optimized system clock switching procedure

V2.0.1-2023/08/04

1. Added CRC polynomial support
2. Updated the process of *adc_ordinary_channel_set* and *adc_preempt_channel_set*
3. Updated relevant notes

V2.0.0-2022/11/18

1. The CRM_HICK48_NODIV is considered the default setting when HICK is used as PLL clock source