Charge Selfvence

turn key _ wit for brush

close Modele Pove relay

Set DI hartbeet to Rut

Check conditions

HB & Run Cor - Off init

Wolit for contector close

close Critical Systems relay

Voit for & PPDM + Nelovity

tell BMs to Charge