

Detailed Diagnostic Report

AI Powered Inspection Analysis

01 May 2026

Generated by DDR AI System

1. Executive Summary

Combined inspection, thermal evidence and AI reasoning used to identify probable defects and corrective actions.

Total Findings Detected: 8

2. Issue Summary Table

#	Observation	Severity
1	The inspection of the 11-floor flat building revealed several issues related to dampness, water	Medium
2	Hall Dampness at skirting level Water leakage from adjacent bathroom Medium Repair ba	Medium
3	Bedroom Dampness at skirting level Water leakage from bathroom Medium Repair bathroom	Medium
4	Kitchen Dampness at skirting level Water leakage from sink or plumbing Medium Repair	Medium
5	Master Bedroom Dampness and efflorescence on wall Water leakage from external wall High	Critical
6	External Wall Cracks and water leakage Structural defect, poor maintenance High Repai	Critical
7	Parking Area Water leakage at ceiling Poor waterproofing, drainage issues Medium Repa	Low
8	Common Bathroom Water leakage, tile hollowness Poor maintenance, inadequate waterproofing	Low

3. Inspection References



imageFile100.png



imageFile101.png




imageFile102.png



imageFile103.png


4. Thermal References



imageFile1.png



imageFile102.png



imageFile103.png



imageFile108.png

5. Detailed Findings

1. Observation

The inspection of the 11-floor flat building revealed several issues related to dampness, water leakage, and structural concerns. The problems were identified in various areas, including the hall, bedrooms, kitchen, bathrooms, and external walls. The root causes of these issues are attributed to poor maintenance, inadequate waterproofing, and structural defects. It is essential to address these problems to prevent further damage and ensure the safety of the occupants.

2. Observation

| Hall | Dampness at skirting level | Water leakage from adjacent bathroom | Medium | Repair bathroom leakage, apply waterproofing coating | High |

3. Observation

| Bedroom | Dampness at skirting level | Water leakage from bathroom | Medium | Repair bathroom leakage, apply waterproofing coating | High |

4. Observation

| Kitchen | Dampness at skirting level | Water leakage from sink or plumbing | Medium | Repair plumbing leakage, apply waterproofing coating | High |

5. Observation

| Master Bedroom | Dampness and efflorescence on wall | Water leakage from external wall | High | Repair external wall leakage, apply waterproofing coating | Critical |

6. Observation

| External Wall | Cracks and water leakage | Structural defect, poor maintenance | High | Repair cracks, apply waterproofing coating, and strengthen structural elements | Critical |

7. Observation

| Parking Area | Water leakage at ceiling | Poor waterproofing, drainage issues | Medium | Repair waterproofing, improve drainage system | High |

8. Observation

| Common Bathroom | Water leakage, tile hollowness | Poor maintenance, inadequate waterproofing | Medium | Repair leakage, replace tiles, apply waterproofing coating | High |

6. Thermal Analysis

Thermal report data reviewed for hidden moisture zones, heat signatures, water ingress paths and temperature anomalies.

Thermal Images Detected: 4

7. AI Root Cause Analysis

****Detailed Diagnostic Report (DDR)****

****1. Executive Summary:****

The inspection of the 11-floor flat building revealed several issues related to dampness, water leakage, and structural concerns. The problems were identified in various areas, including the hall, bedrooms, kitchen, bathrooms, and external walls. The root causes of these issues are attributed to poor maintenance, inadequate waterproofing, and structural defects. It is essential to address these problems to prevent further damage and ensure the safety of the occupants.

****2. Area Wise Findings:****

Area	Problem	Root Cause	Severity	Recommended Solution	Priority
---	---	---	---	---	---
Hall	Dampness at skirting level	Water leakage from adjacent bathroom	Medium	Repair bathroom leakage, apply waterproofing coating	High
Bedroom	Dampness at skirting level	Water leakage from bathroom	Medium	Repair bathroom leakage, apply waterproofing coating	High
Kitchen	Dampness at skirting level	Water leakage from sink or plumbing	Medium	Repair plumbing leakage, apply waterproofing coating	High
Master Bedroom	Dampness and efflorescence on wall	Water leakage from external wall	High	Repair external wall leakage, apply waterproofing coating	Critical
External Wall	Cracks and water leakage	Structural defect, poor maintenance	High	Repair cracks, apply waterproofing coating, and strengthen structural elements	Critical
Parking Area	Water leakage at ceiling	Poor waterproofing, drainage issues	Medium	Repair waterproofing, improve drainage system	High
Common Bathroom	Water leakage, tile hollowness	Poor maintenance, inadequate waterproofing	Medium	Repair leakage, replace tiles, apply waterproofing coating	High

****3. Overall Risks If Delayed:****

- If the identified problems are not addressed promptly, they may lead to more severe consequences, including:
- * Structural damage and collapse
 - * Waterborne diseases and health issues
 - * Electrical hazards and short circuits
 - * Pest infestation and damage to property
 - * Reduced property value and aesthetic appeal

****4. Final Recommendation:****

Based on the inspection findings, it is strongly recommended to:

- * Conduct a comprehensive repair and maintenance program to address the identified problems
- * Engage a qualified contractor to perform the repairs and ensure that the work is done to a high standard
- * Implement a regular maintenance schedule to prevent future issues and ensure the longevity of the building

* Consider hiring a professional project manager to oversee the repair work and ensure that it is completed on time and within budget.

8. Disclaimer

This report is AI-assisted. Final execution decisions should be verified by qualified professionals.