AttenuatorX - Bug # 118: The LEDs displaying attenuation level are in opposite order. MSB should be on the left, like the silkscreen, but it's on the right.

| Status: | New | Priority: High |
|---|------------------------|---|
| Author: | Jack Linke | Category: |
| Created: | 02/11/2013 | Assignee: |
| Updated: | 02/11/2013 | Due date: |
| Subject: The LEDs displaying attenuation level are in opposite order. MSB should be on the left, like the | | enuation level are in opposite order. MSB should be on the left, like the silkscreen, |
| | but it's on the right. | |
| Description | | |
| Reverse the LED order. | | |

History

12/08/2022 1/1