
B - Mechanical Production Engineering MS4092

B - Mechanical Production Engineering MS4092

Number of problems: 8
Start at: 15:30
Finish at: 15:47
Duration: 17 Minutes

Picture below shows carbody structure. What is the well-suited method to fabricate its outer of body shell?



- [x] Extrusion
- [ ] Molding
- [ ] Forming
- [ ] Blanking

Which one of these is correct?

- [ ] Bolt is the fastest way to get two components assembled which need regularly disassembledd. Seaming is good with low ductility material
- [ ] Adhesive bonding used effectively for workpiece with different geometry and properties
- [ ] Seaming is good with low ductility material
- [ ] Solder is a good method for joining material that could afford high temperature joining process

A workpiece with 170 mm length, 15.5 mm diameter gone through a process yields 14.00 mm diameter with lathe machine. With 600 rpm spindle speed and 240 mm/min axial speed. Calculate the process feed rate

$= \frac{240\ mm/min}{600\ rpm}$

$= 0.4\ mm/rev$

- 3,75 mm/min
- 0,4 mm/putaran
- 4,5 putaran/mm
- 2,5 rotasi/mm

Suppose that we want to measure a thickness of a slab using linear measurement devices, choose the correct statement

- None answer correct
- Height gauge will do the most efficient work because its ease of use and re-do the measurement for another objects
- Measuring with micometer will always come up with the best accuracy among other devices because it can reach up to 0,001 mm scale
- Vernier calliper preferable because its less likely has a floating scale reading


Choose one of these options that is not the core business of Industrial 4.0

- Smart Manufacturing
- Data mining and computing
- Additive manufacturing → 5.0
- Industrial Automation

Which is the correct sequence for hole-making process

- Centering; boring; drilling; reaming
- Centering; Boring; Drilling; Reaming
- Centering; reaming; drilling; boring
- Centering; drilling; boring; reaming

Referred to picture below, which tool geometry contribute the most for tool's life?



- [ ] 4
- [ ] 7
- [x] 6
- [ ] 9

Two plates in mass production are going to be connected with more than 3 bolts, if you are a manufacture engineer, how to effectively ensure that all bolts can be completely inserted to all holes?

- [ ] Use a counterbore
- [ ] Using jig while assembly
- [x] Measure these holes to ensure that all properly fabricated in correct coordinates
- [ ] Use a countersink

Kembali Kirim

Jangan pernah mengirimkan sandi melalui Google Formulir.

Konten ini tidak dibuat atau didukung oleh Google. Laporkan Penyalahgunaan - Persyaratan Layanan - Kebijakan Privasi

Google Formulir