

Service Report: 1007**Date:** July 05, 2026**Hospital / Client:** Specialized Medical Center Hospital, B-2 Riyadh.**Device:** Electromagnetic Therapy Device (SALUS TALENT PRO)**Serial Number:** 2309034**Installation Date:** July 23, 2024**Department:** Physiotherapy Dept**Issue Reported:**

The Biomedical Engineering Department at the end-user hospital contacted us on July 4, 2026, to report that the device was not working.

Findings Upon Inspection:

The applicator head housing was found broken, which breached the sealed internal cavity and caused the internal oil to leak out and solidify around the crack.

Action Taken:

The device was withdrawn from the facility and transferred to OrthoServ workshop for applicator replacement.

Important Note:

An attempt was made to repair the applicator head (big); however, the internal fault was found to be extensive, making local repair unfeasible and requiring full replacement of the applicator.

Status:

- Pending Spare Parts

Recommendation

Full replacement of the applicator head is required, as the extent of the crack makes on-site repair unfeasible. The device should remain out of service until the new applicator is installed and function is verified.

Customer Sign	Hospital B.M.E.	Orthoserv Biomedical
		Mahmoud Ghasan

© 2026 OrthoServ

ص.ب. 286869 الرياض 11323 المملكة العربية السعودية. عضوية رقم 34907 هاتف 014806641 فاكس 012419801
P.O.Box 286869 Riyadh 11323 Kingdom of Saudi Arabia Membership No 34907 Tel 014806641 Fax: 012419801

CR: 1010251830 ORTHOPEDIC SERVICE EST