

Service Report: 1008**Date:** July 01, 2026**Hospital / Client:** Specialized Medical Center Hospital, B-1 Riyadh**Device:** Electromagnetic Therapy Device (Salus Talent pro)**Serial Number:** 2309035**Installation Date:** December 06, 2023**Department:** Physiotherapy Dept**Issue Reported:**

The Biomedical Engineering Department at the end-user hospital contacted us to report that the device's applicator head is not functioning and that a burning smell was noticed during operation.

Findings Upon Inspection:

The big applicator head was found completely non-functional, with burnig smell and smoke during operation, indicating an internal electrical fault

Action Taken:

The device was withdrawn from the facility and transferred to OrthoServ workshop for inspection and repair.

Important Note:

It was reported that the facility continued operating the device even after noticing the burning smell and smoke, which increased the risk of further internal damage.

Status:

- Pending Spare Parts

Recommendation

The backlight board must be replaced, with the applicator cover, to fully restore safe and reliable operation of the device.

Customer Sign	Hospital B.M.E.	Orthoserv Biomedical
		Mahmoud Ghasan

© 2026 OrthoServ

ص.ب. 286869 الرياض 11323 المملكة العربية السعودية. عضوية رقم 34907 هاتف 014806641 فاكس 012419801
P.O.Box 286869 Riyadh 11323 Kingdom of Saudi Arabia Membership No 34907 Tel 014806641 Fax: 012419801

CR: 1010251830 ORTHOPEDIC SERVICE EST