

Service Report: 1008**Date:** July 01, 2026**Hospital / Client:** Specialized Medical Center Hospital, B-1 Riyadh**Device:** Electromagnetic Therapy Device (Salus Talent pro)**Serial Number:** 2309035**Installation Date:** December 06, 2023**Department:** Physiotherapy Dept**Issue Reported:**

The Biomedical Engineering Department at the end-user hospital contacted us to report that the device's applicator head is not functioning and that a burning smell was noticed during operation.

Findings Upon Inspection:

The applicator head (big) was found completely non-functional, with burnig smell and smoke during operation, indicating an internal electrical fault

Action Taken:

The device was withdrawn from the facility and transferred to OrthoServ workshop for inspection and repair.

Important Note:

It was reported that the facility continued operating the device even after noticing the burning smell and smoke, which increased the risk of further internal damage.

Status:

- Pending Spare Parts

Recommendation

After extended operation, the device tends to overheat; it is recommended to switch off the unit for approximately five minutes to allow it to cool down before resuming use.

Customer Sign	Hospital B.M.E.	Orthoserv Biomedical
		Mahmoud Ghasan

© 2026 OrthoServ

ص.ب. 286869 الرياض 11323 المملكة العربية السعودية. عضوية رقم 34907 هاتف 014806641 فاكس 012419801
P.O.Box 286869 Riyadh 11323 Kingdom of Saudi Arabia Membership No 34907 Tel 014806641 Fax: 012419801

CR: 1010251830 ORTHOPEDIC SERVICE EST