

Service Report: 1008**Date:** July 01, 2026**Hospital / Client:** Specialized Medical Center Hospital, B-1 Riyadh**Device:** Electromagnetic Therapy Device (Salus Talent pro)**Serial Number:** 2309035**Installation Date:** December 06, 2023**Department:** Physiotherapy Dept**Issue Reported:**

The Biomedical Engineering Department at the end-user hospital contacted us to report that the device's applicator head is not functioning and was emitting smoke during operation.

Findings Upon Inspection:

The applicator head was found completely non-functional, with visible smoke emitted during operation, indicating an internal electrical fault.

Action Taken:

The device was withdrawn from the facility and transferred to OrthoServ workshop for inspection and repair.

Important Note:

This unit was previously repaired on 24/08/2025, at which time we recommended replacing the Bakelite board with capacitor due to low intensity output. As this recommendation was not actioned, the unit has now developed a complete failure with smoke emission during operation.

Status:

- Pending Spare Parts

Recommendation

Immediate replacement of the Bakelite board with capacitor is required, as the previously identified fault was left unaddressed and has now progressed to complete failure with smoke emission. Continued operation without replacement risks further internal damage and safety hazards. The device must remain out of service until the new board is installed and function is verified.

Customer Sign	Hospital B.M.E.	Orthoserv Biomedical
		Mahmoud Ghasan

© 2026 OrthoServ