

Service Report: 1007**Date:** July 05, 2026**Hospital / Client:** Specialized Medical Center Hospital, B-2 Riyadh.**Device:** Electromagnetic Therapy Device (SALUS TALENT PRO)**Serial Number:** 2309034**Installation Date:** July 23, 2024**Department:** Physiotherapy Dept**Issue Reported:**

The Biomedical Engineering Department at the end-user hospital contacted us on July 4, 2026, to report that the device was not working.

Findings Upon Inspection:

The big applicator head housing was found broken, which breached the sealed internal cavity and caused the internal oil to leak out and solidify around the crack.

Action Taken:

The device was withdrawn from the facility and transferred to OrthoServ workshop for applicator replacement.

Important Note:

An attempt was made to repair the big applicator however, the fault appears to be caused by mishandling, and local repair is not feasible. Full replacement of the applicator is required.

Status:

- Pending Spare Parts

Recommendation

Customer Sign	Hospital B.M.E.	Orthoserv Biomedical
		Mahmoud Ghasan

© 2026 OrthoServ

ص.ب. 286869 الرياض 11323 المملكة العربية السعودية. عضوية رقم 34907 هاتف 014806641 فاكس 012419801
P.O.Box 286869 Riyadh 11323 Kingdom of Saudi Arabia Membership No 34907 Tel 014806641 Fax: 012419801

CR: 1010251830 ORTHOPEDIC SERVICE EST