Supplementary Repair Estimate

Vehicle: TN-07-AX-3921

Garage: Rajan Motors Service Centre
Estimate Date: 22-Oct-2026
Customer: Arun Vijayan
Ref: Supplementary to original estimate dated 17-Oct-2026

Additional damage discovered during disassembly -- rear and side items:

S.No	Description	Type	Amount (Rs)
1	Rear bumper -- removal, repair and repaint	Labour + Paint	14,200
2	Rear-right side panel -- dent pulling and repaint	Labour + Paint	11,500
3	Tail-light assembly (RHS) -- replacement	Part + Labour	8,900
4	Boot lid -- realignment	Labour	3,000
5	Rear parking sensor recalibration	Service	2,200
		Sub-Total	**39,800**
		GST (18%)	**7,164**
		TOTAL	**46,964**

Combined Total (Original + Supplementary): Rs 67,024 + Rs 46,964 = **Rs 1,13,988**

Authorised by: K. Rajan, Service Manager, Rajan Motors Service Centre