

MRPL - FIRE SAFETY INCIDENT LOG

Facility: Central Fire Station & Tank Farm 6

Classification: RESTRICTED - PLANT SECURITY

Incident Summary:

Mechanical seal leakage on Transfer Pump TP-12 resulted in fugitive Naptha vapor accumulation near Tank Farm 6. Automated nitrogen blanketing successfully suppressed the vapor cloud.

Safety Directives:

1. All centrifugal pumps handling Class-A hydrocarbons in Tank Farm 6 must be retrofitted with dual-mechanical cartridge seals following Protocol F-9.
2. UV/IR flame detectors at Bay 4 must be recalibrated bi-weekly.