

MRPL REFINERY - UNIT 3 SAFETY AUDIT

Executive Summary:

Routine maintenance checks were conducted on Unit 3 (Fluid Catalytic Cracking Unit). Critical findings include severe corrosion and minor oil leakage on Pressure Relief Valve #402. This violates ISO-9001.

Mandatory Action Plan:

Immediate replacement of Pressure Relief Valve #402 is required before restarting Unit 3. Maintenance team must strictly follow Protocol B-7.