FICTIONAL ASSESSMENT FIXTURE

Same-incident inspection report

Reference and date

Incident IMG_001 / inspection INS-001 / 22 September 2026. This report concerns the same burst-pipe incident as the kitchen photograph.

Observed cause

A pipe connection beneath the kitchen sink failed. The water supply has been isolated. There is no evidence of external surface-water flooding.

Confirmed affected scope

There is moderate water damage in exactly two rooms: the kitchen and the adjacent dining room. The kitchen photograph shows only the kitchen. Inspection of the dining room confirms wet flooring and water-damaged skirting. Other rooms are dry. Count each room once.

Action for the adjuster

Use the full inspected scope when preparing the triage report. Arrange drying and a qualified repair assessment. This document does not establish insurance eligibility or authorise a settlement.

Synthetic training material. Not a real inspection, invoice, insurance decision or payment commitment.