Step 1:

calculate all (N-k)v possibilities one further austenitic grain of the RVE could transform

Step 2:

Evaluate the grain-laminate pair that minimizes the systems specific free energy φ

Step 3:

Generate new input files, where the found grain-laminate pair from Step 2 has already transformed (k = k +1)