



FLIGHT OPERATIONS LETTER RECORD

1. GENERAL

For the sake of accountability, first editions of the Flight Operations Letters (FOL) are sequentially numbered on a yearly basis. The Flight Operations Letter revisions carry both the first edition and the revision dates, and the original number remains the same.

The FOL STATUS column in the FLIGHT OPERATIONS LETTERS RECORD sheets is intended to be filled in with the conditions stated below as applicable:

IN EFFECT

It means that the FOL contains current and pertinent information, which is not otherwise covered in other operational publication or was revised to update its content.

INCORPORATED

It means that appropriate information has been incorporated in the pertinent publications, and the FOL may be disregarded.

CANCELLED

It means that the FOL is no longer in effect and should be disregarded.

The FLIGHT OPERATIONS LETTERS INDEX sheets present the titles of the FOLs published by Embraer from 2010 up to the date of this issuing.

The FLIGHT OPERATIONS LETTERS SUBJECT INDEX summarizes all the documents according to the subject that the letter is related to.

For your easier control, complete the FLIGHT OPERATIONS LETTERS RECORD and the FLIGHT OPERATIONS LETTERS INDEX sheets upon receipt the Flight Operations Letters.

INDEX

INTENTIONALLY BLANK



2. FOL INDEX

- * FOL PHE505-001/10 - BRAKE OPERATIONAL RECOMMENDATION
- ** FOL PHE505-002/10 - AIRCRAFT POWER-UP UNDER COLD WEATHER
- * FOL PHE505-001/11 - OPERA INSTALLATION PROCEDURES
- * FOL PHE505-002/11 - PUSHER FAIL MESSAGE DURING PRE-FLIGHT TEST
- * FOL PHE505-003/11 - FUEL USED UNEXPECTED VALUE
- ** FOL PHE505-004/11 - CONTAMINATED RUNWAY DATA (ANAC OPERATORS)
- ** FOL PHE505-005/11 - CONTAMINATED RUNWAY DATA (FAA OPERATORS)
- ** FOL PHE505-006/11 - BRAKE COOLING TIME
- * FOL PHE505-007/11 - AIRCRAFT POWER-UP
- ** FOL PHE505-008/11 - RUDDER GUST LOCK FAILURE IN THE LOCKED POSITION
- ** FOL PHE505-009/11 - OPERATION IN ICING CONDITIONS ABOVE 30000 FT
- ** FOL PHE505-010/11 - THRUST RATES FOR TAKE-OFF AND CRUISE
- ** FOL PHE505-011/11 - ENGINE START UP RECOMMENDATIONS
- ** FOL PHE505-012/11 - DISPLAY BRIGHTNESS ADJUSTMENT
- FOL PHE505-013/11 - BATTERY RECOMMENDATIONS

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

- * FOL PHE505-014/11 - CANCELLATION OF OPERATIONAL
BULLETIN 505-001-11 – LANDING
DISTANCE FACTOR
RECOMMENDATION
- * FOL PHE505-015/11 - RECOMMENDED PROCEDURES FOR
FCE RELATED CAS MESSAGES
- ** FOL PHE505-001/12 - HYDRAULIC SYSTEM SERVICING
FOL PHE505-002/12 - AHRS 1 (2) FAILURE DUE TO
SUSTAINED BANK TURNS
- * FOL PHE505-003/12 - OPERA LEVEL-OFF ALTITUDE OUTPUT
ISSUE
- * FOL PHE505-004/12 - IESI MAGNETIC HEADING AMBER
CROSS
- ** FOL PHE505-005/12 - NEW PROCEDURE FOR HYD SYS
ACCUMULATOR PRE-CHARGE CHECK
FOL PHE505-006/12 - ICAO FLIGHT PLAN CAPABILITIES
FOL PHE505-007/12 - ATN/VDL MODE 2 CPDLC MANDATE
STATUS
FOL PHE505-001/13 - BATTERY RECOMMENDATIONS ON
GROUND OPERATIONS
- ** FOL PHE505-002/13 - ACTIVATION OF THE FLAP FULL
POSITION
FOL PHE505-003/13 - SLIGHT VIBRATION DURING FLAP
TRANSITION
- * FOL PHE505-004/13 - G3000 AVIONICS MISBEHAVIOR
- ** FOL PHE505-005/13 - OXYGEN CREW MASK INSTALLATION
PROCEDURE
- ** FOL PHE505-006/13 - ENGINE DOES NOT START (S/GEN
DOES NOT START TO RUN)

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX



- * FOL PHE505-007/13 - INSPECTION OF THE MLG PRESSURE PLATE
- ** FOL PHE505-008/13 - BOTH ON GPS1(2) IN THE REVERSIONARY WINDOW
- * FOL PHE505-009/13 - MISBEHAVIOR DURING MFD TRANSITION FROM REVERSIONARY TO NORMAL MODE
- ** FOL PHE505-010/13 - BRAKE OPERATIONAL RECOMMENDATIONS
- FOL PHE505-011/13 - ECS RECOMMENDATIONS DURING COLD WEATHER OPERATIONS
- ** FOL PHE505-012/13 - ALTERNATIVE CMC DOWNLOAD PROCEDURE FOR AIRCRAFT EQUIPPED WITH G1000 LOAD 63.7
- ** FOL PHE505-013/13 - INCREASE IN LANDING GEAR EXTENSION TIME
- ** FOL PHE505-001/14 - FUEL SYSTEM SPURIOUS MESSAGES BEING TRIGGERED DUE TO WRONG NAVIGATION DATABASE UPDATE PROCEDURE
- FOL PHE505-002/14 - RECOMMENDATIONS BEFORE TURNING ON THE ANTI-ICE SYSTEM BELOW 13000 FT
- ** FOL PHE505-003/14 - RADAR ALTIMETER INDICATION OSCILLATION ON GROUND
- ** FOL PHE505-004/14 - PRESN AUTO FAIL
- ** FOL PHE505-005/14 - G1000 LOAD 63.7 (0734.6D) AVIONICS ISSUES & NEW FEATURES
- ** FOL PHE505-006/14 - NEW ENGINE OIL SIGHT GLASS AND REVISED SERVICING PROCEDURE

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

FOL PHE505-007/14 - RECOMMENDED TIRE PRACTICES

** FOL PHE505-008/14 - LAVATORY LEAKAGE DUE TO DEBRIS
BLOCKING DRAIN VALVE

FOL PHE505-009/14 - OXYGEN MASK CONNECTOR

** FOL PHE505-010/14 - ECS TRANSITORY CONDITION DURING
CLIMB AND INITIAL CRUISE

* FOL PHE505-011/14 - EASA OPERA VERSION 8.0 & 8.1
INSTALL RECOMMENDATIONS

** FOL PHE505-012/14 - SPURIOUS FUEL PUMP CAS MESSAGE
DURING AIRCRAFT POWER UP

FOL PHE505-013/14 - NOISE DURING LANDING GEAR
RETRACTION

** FOL PHE505-014/14 - POLYURETHANE EROSION TAPE
WEAR

** FOL PHE505-015/14 - IESI MISBEHAVIOR DURING AIRCRAFT
POWER UP

** FOL PHE505-016/14 - ATTITUDE AND HEADING
MISBEHAVIOR ON GROUND

FOL PHE505-017/14 - ADS-B OUT STATUS

** FOL PHE505-018/14 - LANDING PROCEDURE BEST
PRACTICES AND RECOMMENDATIONS

FOL PHE505-019/14 - MOMENTARY LATERAL SHIFT ON SVT
AND CHANGE IN FMS-COUPLED AFCS
MODE UNDER CERTAIN CONDITIONS
(GARMIN'S SERVICE ALERT 1472)

** FOL PHE505-001/15 - CLARIFICATION ON MEL ITEM 21-21-01
– FLOW CONTROL SHUTOFF VALVES
(FCSOV)

* FOL PHE505-002/15 - COMMON TYPE RATING - PILOT'S
LICENSE ENDORSEMENT

* **CANCELLED Flight Operations Letters**

** **INCORPORATED Flight Operations Letters**

INDEX



- ** FOL PHE505-003/15 - INCREASE IN PITCH ANGLE
COMMANDED BY AUTOPILOT WHILE
INTERCEPTING THE ILS GLIDESLOPE
SIGNAL
- * FOL PHE505-004/15 - TRANSPORT OF LITHIUM BATTERIES
AS CARGO
- ** FOL PHE505-001/16 - WORLDWIDE NAVIGATION DATABASE
RESTRICTION (GARMIN'S SERVICE
ADVISORY Nº1604 REV A)
- ** FOL PHE505-002/16 - G3000 AVIONICS SOFTWARE LOAD
13.25 PILOT'S TRAINING
REQUIREMENT
- ** FOL PHE505-003/16 - ALKALI ORGANIC SALT-BASED
AIRCRAFT DE-ICING
- ** FOL PHE505-004/16 - G1000 AVIONICS SOFTWARE LOAD
83.25 PILOT'S TRAINING
REQUIREMENT
- FOL PHE505-005/16 - BRAKE FAILURE WHEN LANDING WITH
WHEELS SPIN UP AND NO WEIGHT ON
WHEELS
- FOL PHE505-006/16 - FLIGHT PLANNING
RECOMMENDATIONS FOR NOTAM
AREAS AFFECTED BY GPS SIGNAL
UNAVAILABILITY
- FOL PHE505-007/16 - CAUTION CAS MESSAGES NOT LISTED
IN EMBRAER MANUALS
- FOL PHE505-008/16 - TCAS TARGETS NOT DISPLAYED IN
SYNTHETIC VISION
- * FOL PHE505-009/16 - 2015 IGRF (INTERNATIONAL
GEOMAGNETIC REFERENCE FIELD)
MAGNETIC FIELD MODEL UPDATE

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

- * FOL PHE505-010/16 - SPURIOUS INTERMITTENT MULTIPLE CAS MESSAGES
- FOL PHE505-001/18 - ENGINE IGNITION CHANNEL A COMMANDED ON SUBSEQUENT STARTS
- FOL PHE505-001/19 - GROUND RESET FOR FCE FAILURES
- ** FOL PHE505-002/19 - PITCH-UP ATTITUDE COMMAND AFTER LOSS OF FLAP POSITION INDICATION
- FOL PHE505-003/19 - SPURIOUS A-I WINGSTAB ON CAS MESSAGE DURING TAKEOFF RUN IN HOT WEATHER OPERATIONS
- FOL PHE505-004/19 - INTERMITTENT AHRS DUAL FAILURE INFLIGHT
- FOL PHE505-001/20 - AIR CONDITIONING BEST PRACTICES FOR HIGH EXTERNAL TEMPERATURES
- FOL PHE505-002/20 - EUROCONTROL LOGON LIST APPLICATION GUIDANCE
- FOL PHE505-003/20 - TOLD OPERATION CLARIFICATION
- ** FOL PHE505-004/20 - SPURIOUS ROAAS NO DATA CAS MESSAGE
- FOL PHE505-005/20 - INSTRUCTIONS ON OPERATIONAL SOFTWARE IDENTIFICATION
- FOL PHE505-006/20 - GTC BLINKING AND RETURNING TO HOME SCREEN
- FOL PHE505-001/21 - PARK BRAKE LIGHT NOT EXTINGUISHING DURING COLD WEATHER
- FOL PHE505-002/21 - SPURIOUS RADIAL WX RADAR TARGET RETURN

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

FOL PHE505-001/22 - 5G C-BAND POTENTIAL
INTERFERENCE ON RADAR
ALTIMETERS

FOL PHE505-002/22 - USE OF SUSTAINABLE AVIATION FUEL
(SAF)

* FOL PHE505-003/22 - ECL PROCEDURES INCORRECTLY
DISPLAYED

** FOL PHE505-001/23 - TRANSITION FROM VNAV PATH MODE
TO GS/GP MODES DURING APPROACH

FOL PHE505-002/23 - CRITICAL FUEL SCENARIOS FOR THE
NEW EASA FUEL/ENERGY RULES

** FOL PHE505-003/23 - SWPS BEHAVIOR IN CASE OF A-I
WINGSTB FAIL AND A-I WINGSTB LEAK

** FOL PHE505-004/23 - GNSS DATA DEGRADATION
AWARENESS

FOL PHE505-001/24 - DEACTIVATION OF THE CDM FOR
DISPATCH WITH VCS INOPERATIVE

FOL PHE505-002/24 - EMERGENCY/PARKING BRAKE LIGHT
ON DURING LANDING GEAR
RETRACTION

** FOL PHE505-003/24 - OPERATIONAL PROCEDURE TO TEST
THE RAM AIR VALVE ACTUATION FOR
DISPATCH WITH FCSOV INOPERATIVE

FOL PHE505-001/25 - STICK PUSHER ACTIVATION AFTER
AIRSPEED MISCOMPARE

FOL PHE505-001/26 - RUDDER GUST LOCK INADVERTENT
RELEASE

FOL PHE505-002/26 - EMERGENCY EVACUATION
ANNOUNCEMENT IN PARTIAL OR
GEAR UP LANDINGS

* **CANCELLED Flight Operations Letters**

** **INCORPORATED Flight Operations Letters**

INDEX

FOL PHE505-003/26 - SPURIOUS A-I WINGSTB FAIL CAS
MESSAGE DURING ENGINE
SHUTDOWN IN HOT WEATHER
OPERATIONS

User: andreiap0t - Printed by TechPubs - Aug 07/26 - 10:28:19

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

3. FLIGHT OPERATIONS LETTERS SUBJECT INDEX

AIRPLANE GENERAL

FOL PHE505-006/12 - ICAO FLIGHT PLAN CAPABILITIES

FOL PHE505-007/12 - ATN/VDL MODE 2 CPDLC MANDATE
STATUS

** FOL PHE505-008/14 – LAVATORY LEAKAGE DUE TO DEBRIS
BLOCKING DRAIN VALVE

* FOL PHE505-002/15 - COMMON TYPE RATING - PILOT'S
LICENSE ENDORSEMENT

* FOL PHE505-004/15 - TRANSPORT OF LITHIUM BATTERIES
AS CARGO

** FOL PHE505-002/16 - G3000 AVIONICS SOFTWARE LOAD
13.25 PILOT'S TRAINING
REQUIREMENT

** FOL PHE505-004/16 - G1000 AVIONICS SOFTWARE LOAD
83.25 PILOT'S TRAINING
REQUIREMENT

FOL PHE505-006/16 - FLIGHT PLANNING
RECOMMENDATIONS FOR NOTAM
AREAS AFFECTED BY GPS SIGNAL
UNAVAILABILITY

FOL PHE505-002/20 - EUROCONTROL LOGON LIST
APPLICATION GUIDANCE

FOL PHE505-003/20 - TOLD OPERATION CLARIFICATION

* FOL PHE505-003/22 - ECL PROCEDURES INCORRECTLY
DISPLAYED

FOL PHE505-002/26 - EMERGENCY EVACUATION
ANNOUNCEMENT IN PARTIAL OR
GEAR UP LANDINGS

* **CANCELLED Flight Operations Letters**

** **INCORPORATED Flight Operations Letters**

INDEX

AIR CONDITIONING, PNEUMATICS & PRESSURIZATION

FOL PHE505-011/13 - ECS RECOMMENDATIONS DURING
COLD WEATHER OPERATIONS

FOL PHE505-002/14 - RECOMMENDATIONS BEFORE
TURNING ON THE ANTI-ICE SYSTEM
BELOW 13000 FT

** FOL PHE505-004/14 - PRESN AUTO FAIL

** FOL PHE505-010/14 - ECS TRANSITORY CONDITION DURING
CLIMB AND INITIAL CRUISE

** FOL PHE505-001/15 - CLARIFICATION ON MEL ITEM 21-21-01
– FLOW CONTROL SHUTOFF VALVES
(FCSOV)

FOL PHE505-001/20 - AIR CONDITIONING BEST PRACTICES
FOR HIGH EXTERNAL TEMPERATURES

FOL PHE505-001/24 - DEACTIVATION OF THE CDM FOR
DISPATCH WITH VCS INOPERATIVE

** FOL PHE505-003/24 - OPERATIONAL PROCEDURE TO TEST
THE RAM AIR VALVE ACTUATION FOR
DISPATCH WITH FCSOV INOPERATIVE

AUTOPILOT, FLIGHT INSTRUMENTS & NAVIGATION

** FOL PHE505-012/11 - DISPLAY BRIGHTNESS ADJUSTMENT

FOL PHE505-002/12 - AHRS 1 (2) FAILURE DUE TO
SUSTAINED BANK TURNS

* FOL PHE505-004/12 - IESI MAGNETIC HEADING AMBER
CROSS

* FOL PHE505-004/13 - G3000 AVIONICS MISBEHAVIOR

** FOL PHE505-008/13 - BOTH ON GPS1 (2) IN THE
REVERSIONARY WINDOW

* **CANCELLED Flight Operations Letters**

** **INCORPORATED Flight Operations Letters**

INDEX

AUTOPILOT, FLIGHT INSTRUMENTS & NAVIGATION (continued)

- * FOL PHE505-009/13 - MISBEHAVIOR DURING MFD
TRANSITION FROM REVERSIONARY
TO NORMAL MODE
- ** FOL PHE505-012/13 - ALTERNATIVE CMC DOWNLOAD
PROCEDURE FOR AIRCRAFT
EQUIPPED WITH G1000 LOAD 63.7
- ** FOL PHE505-003/14 - RADAR ALTIMETER INDICATION
OSCILLATION ON GROUND
- ** FOL PHE505-005/14 - G1000 LOAD 63.7 (0734.6D) AVIONICS
ISSUES & NEW FEATURES
- ** FOL PHE505-015/14 - IESI MISBEHAVIOR DURING AIRCRAFT
POWER UP
- ** FOL PHE505-016/14 - ATTITUDE AND HEADING
MISBEHAVIOR ON GROUND
- FOL PHE505-017/14 - ADS-B OUT STATUS
- FOL PHE505-019/14 - MOMENTARY LATERAL SHIFT ON SVT
AND CHANGE IN FMS-COUPLED AFCS
MODE UNDER CERTAIN CONDITIONS
(GARMIN'S SERVICE ALERT 1472)
- ** FOL PHE505-003/15 - INCREASE IN PITCH ANGLE
COMMANDED BY AUTOPILOT WHILE
INTERCEPTING THE ILS GLIDESLOPE
SIGNAL
- ** FOL PHE505-001/16 - WORLDWIDE NAVIGATION DATABASE
RESTRICTION (GARMIN'S SERVICE
ADVISORY N°1604 REV A)
- FOL PHE505-007/16 - CAUTION CAS MESSAGES NOT LISTED
IN EMBRAER MANUALS
- * FOL PHE505-009/16 - 2015 IGRF (INTERNATIONAL
GEOMAGNETIC REFERENCE FIELD)
MAGNETIC FIELD MODEL UPDATE
- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

AUTOPILOT, FLIGHT INSTRUMENTS & NAVIGATION (continued)

- * FOL PHE505-010/16 - SPURIOUS INTERMITTENT MULTIPLE CAS MESSAGES
- FOL PHE505-004/19 - INTERMITTENT AHRS DUAL FAILURE INFLIGHT
- FOL PHE505-006/20 - GTC BLINKING AND RETURNING TO HOME SCREEN
- FOL PHE505-002/21 - SUBJECT: SPURIOUS RADIAL WX RADAR TARGET RETURN
- FOL PHE505-001/22 - 5G C-BAND POTENTIAL INTERFERENCE ON RADAR ALTIMETERS
- ** FOL PHE505-001/23 - TRANSITION FROM VNAV PATH MODE TO GS/GP MODES DURING APPROACH
- ** FOL PHE505-004/23 - GNSS DATA DEGRADATION AWARENESS

ELECTRICAL & LIGHTING

- FOL PHE505-013/11 - BATTERY RECOMMENDATIONS
- FOL PHE505-001/13 - BATTERY RECOMMENDATIONS ON GROUND OPERATIONS

FUEL SYSTEM

- * FOL PHE505-003/11 - FUEL USED UNEXPECTED VALUE
- ** FOL PHE505-001/14 - FUEL SYSTEM SPURIOUS MESSAGES BEING TRIGGERED DUE TO WRONG NAVIGATION DATABASE UPDATE PROCEDURE

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

FUEL SYSTEM (continued)

- ** FOL PHE505-012/14 - SPURIOUS FUEL PUMP CAS MESSAGE DURING AIRCRAFT POWER UP
- FOL PHE505-002/22 - USE OF SUSTAINABLE AVIATION FUEL (SAF)
- FOL PHE505-002/23 - CRITICAL FUEL SCENARIOS FOR THE NEW EASA FUEL/ENERGY RULES

FLIGHT CONTROLS

- ** FOL PHE505-002/10 - AIRCRAFT POWER-UP UNDER COLD WEATHER
- * FOL PHE505-007/11 - AIRCRAFT POWER-UP
- ** FOL PHE505-008/11 - RUDDER GUST LOCK FAILURE IN THE LOCKED POSITION
- * FOL PHE505-015/11 - RECOMMENDED PROCEDURES FOR FCE RELATED CAS MESSAGES
- ** FOL PHE505-002/13 - ACTIVATION OF THE FLAP FULL POSITION
- FOL PHE505-003/13 - SLIGHT VIBRATION DURING FLAP TRANSITION
- FOL PHE505-001/19 - GROUND RESET FOR FCE FAILURES
- ** FOL PHE505-002/19 - PITCH-UP ATTITUDE COMMAND AFTER LOSS OF FLAP POSITION INDICATION
- FOL PHE505-001/25 - STICK PUSHER ACTIVATION AFTER AIRSPEED MISCOMPARE
- FOL PHE505-001/26 - RUDDER GUST LOCK INADVERTENT RELEASE

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

HYDRAULIC

- ** FOL PHE505-001/12 - HYDRAULIC SYSTEM SERVICING
- ** FOL PHE505-005/12 - NEW PROCEDURE FOR HYD SYS
ACCUMULATOR PRE-CHARGE CHECK

ICE AND RAIN PROTECTION

- ** FOL PHE505-003/16 - ALKALI ORGANIC SALT-BASED
AIRCRAFT DE-ICING
- FOL PHE505-003/19 - SPURIOUS A-I WINGSTAB ON CAS
MESSAGE DURING TAKEOFF RUN IN
HOT WEATHER OPERATIONS
- FOL PHE505-003/26 - SPURIOUS A-I WINGSTB FAIL CAS
MESSAGE DURING ENGINE
SHUTDOWN IN HOT WEATHER
OPERATIONS

User: andreiap0t - Printed by TechPubs - Aug 07/26 - 10:28:19

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX



LANDING GEAR & BRAKES

- * FOL PHE505-001/10 - BRAKE OPERATIONAL RECOMMENDATION
- ** FOL PHE505-006/11 - BRAKE COOLING TIME
- * FOL PHE505-014/11 - CANCELLATION OF OPERATIONAL BULLETIN 505-001-11 – LANDING DISTANCE FACTOR RECOMMENDATION
- * FOL PHE505-007/13 - INSPECTION OF THE MLG PRESSURE PLATE
- ** FOL PHE505-010/13 - BRAKE OPERATIONAL RECOMMENDATIONS
- ** FOL PHE505-013/13 - INCREASE IN LANDING GEAR EXTENSION TIME
- FOL PHE505-007/14 - RECOMMENDED TIRE PRACTICES
- FOL PHE505-013/14 - NOISE DURING LANDING GEAR RETRACTION
- FOL PHE505-005/16 - BRAKE FAILURE WHEN LANDING WITH WHEELS SPIN UP AND NO WEIGHT ON WHEELS
- FOL PHE505-001/21 - PARK BRAKE LIGHT NOT EXTINGUISHING DURING COLD WEATHER
- FOL PHE505-002/24 - EMERGENCY/PARKING BRAKE LIGHT ON DURING LANDING GEAR RETRACTION

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

OXYGEN

- ** FOL PHE505-005/13 - OXYGEN CREW MASK INSTALLATION
PROCEDURE
- FOL PHE505-009/14 - OXYGEN MASK CONNECTOR

PERFORMANCE

- ** FOL PHE505-004/11 - CONTAMINATED RUNWAY DATA
(ANAC OPERATORS)
- ** FOL PHE505-005/11 - CONTAMINATED RUNWAY DATA (FAA
OPERATORS)
- ** FOL PHE505-009/11 - OPERATION IN ICING CONDITIONS
ABOVE 30000 FT
- ** FOL PHE505-018/14 - LANDING PROCEDURE BEST
PRACTICES AND RECOMMENDATIONS

POWERPLANT

- ** FOL PHE505-010/11 - THRUST RATES FOR TAKE-OFF AND
CRUISE
- ** FOL PHE505-011/11 - ENGINE START UP
RECOMMENDATIONS
- ** FOL PHE505-006/13 - ENGINE DOES NOT START (S/GEN
DOES NOT START TO RUN)
- ** FOL PHE505-006/14 - NEW ENGINE OIL SIGHT GLASS AND
REVISED SERVICING PROCEDURE
- FOL PHE505-001/18 - ENGINE IGNITION CHANNEL A
COMMANDED ON SUBSEQUENT
STARTS

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX



SOFTWARE

- * FOL PHE505-001/11 - OPERA INSTALLATION PROCEDURES
- * FOL PHE505-003/12 - OPERA LEVEL-OFF ALTITUDE OUTPUT ISSUE
- * FOL PHE505-011/14 - EASA OPERA VERSION 8.0 & 8.1 INSTALL RECOMMENDATIONS
- FOL PHE505-005/20 - INSTRUCTIONS ON OPERATIONAL SOFTWARE IDENTIFICATION

STRUCTURE

- ** FOL PHE505-014/14 - POLYURETHANE EROSION TAPE WEAR

WARNING

- * FOL PHE505-002/11 - PUSHER FAIL MESSAGE DURING PRE-FLIGHT TEST
- FOL PHE505-008/16 - TCAS TARGETS NOT DISPLAYED IN SYNTHETIC VISION
- ** FOL PHE505-004/20 - SPURIOUS ROAAS NO DATA CAS MESSAGE
- ** FOL PHE505-003/23 - SWPS BEHAVIOR IN CASE OF A-I WINGSTB FAIL AND A-I WINGSTB LEAK

- * **CANCELLED Flight Operations Letters**
- ** **INCORPORATED Flight Operations Letters**

INDEX

INTENTIONALLY BLANK

4. FLIGHT OPERATIONS LETTERS RECORD

FOL NUMBER	ISSUED DATE (Revision Date)	FOL STATUS	REMARKS
FOL PHE505-001/10	Dec 07, 2010	CANCELLED	SB or factory modification incorporated in entire fleet
FOL PHE505-002/10	Dec 09, 2010	INCORPORATED	SB or factory modification incorporated in entire fleet
FOL PHE505-001/11	Feb 18, 2011	CANCELLED	Software update
FOL PHE505-002/11	Feb 18, 2011	CANCELLED	SB or factory modification incorporated in entire fleet
FOL PHE505-003/11	Feb 18, 2011	CANCELLED	SB or factory modification incorporated in entire fleet
FOL PHE505-004/11	Feb 24, 2011	INCORPORATED	Information incorporated on Manuals
FOL PHE505-005/11	Feb 24, 2011	INCORPORATED	Information incorporated on Manuals
FOL PHE505-006/11	Mar 04, 2011	INCORPORATED	Information incorporated on POH section 5-10-25
FOL PHE505-007/11	Mar 28, 2011	CANCELLED	Information incorporated on Manuals
FOL PHE505-008/11	Apr 05, 2011	INCORPORATED	Information incorporated on POH section 3-18
FOL PHE505-009/11	Apr 12, 2011	INCORPORATED	Information incorporated on AFM

INDEX

FLIGHT OPERATIONS LETTER



FOL NUMBER	ISSUED DATE (Revision Date)	FOL STATUS	REMARKS
FOL PHE505-010/11	May 20, 2011 (Jun 18, 2018)	INCORPORATED	Information incorporated on POH section 9-05-10
FOL PHE505-011/11	Jun 10, 2011	INCORPORATED	Information incorporated on POH sections 3-15, 9-05-20 and AFM section 2-40
FOL PHE505-012/11	Jul 08, 2011	INCORPORATED	Information incorporated on ACFOG
FOL PHE505-013/11	Sep 22, 2011 (Jun 18, 2018)	IN EFFECT	Revision 04
FOL PHE505-014/11	Nov 22, 2011	CANCELLED	Outdated information
FOL PHE505-015/11	Dec 09, 2011 (Jun 18, 2018)	CANCELLED	SB or factory modification incorporated in entire fleet
FOL PHE505-001/12	Mar 02, 2012	INCORPORATED	Information incorporated on POH section 8-40
FOL PHE505-002/12	Jun 29, 2012 (Feb 20, 2024)	IN EFFECT	Revision 02
FOL PHE505-003/12	Jul 10, 2012	CANCELLED	Software update
FOL PHE505-004/12	Jul 30, 2012	CANCELLED	Information incorporated on FOL PHE505-015/14
FOL PHE505-005/12	Aug 13, 2012	INCORPORATED	Information incorporated on POH section 8-40
FOL PHE505-006/12	Oct 08, 2012 (Apr 28, 2026)	IN EFFECT	Revision 11
FOL PHE505-007/12	Dec 21, 2012 (Jun 18, 2018)	IN EFFECT	Revision 08
FOL PHE505-001/13	Feb 08, 2013 (Jun 18, 2018)	IN EFFECT	Revision 05
FOL PHE505-002/13	May 02, 2013 (Jun 18, 2018)	INCORPORATED	Information incorporated on AFM, POH and QRH
FOL PHE505-003/13	Jul 02, 2013 (Jun 18, 2018)	IN EFFECT	Revision 03

INDEX

FOL NUMBER	ISSUED DATE (Revision Date)	FOL STATUS	REMARKS
FOL PHE505-004/13	Jul 19, 2013	CANCELLED	SB or factory modification incorporated in entire fleet
FOL PHE505-005/13	Jul 19, 2013	INCORPORATED	Information incorporated on POH section 9-13-10
FOL PHE505-006/13	Aug 09, 2013 (Jun 18, 2018)	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-007/13	Sep 13, 2013	CANCELLED	SB or factory modification incorporated in entire fleet
FOL PHE505-008/13	Oct 04, 2013 (Jun 18, 2018)	INCORPORATED	Information incorporated on POH section 2-45 and AFM section 2-56
FOL PHE505-009/13	Nov 11, 2013	CANCELLED	Information incorporated on FOL PHE505-005/14
FOL PHE505-010/13	Dec 17, 2013	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-011/13	Nov 14, 2013 (Apr 28, 2026)	IN EFFECT	Revision 05
FOL PHE505-012/13	Dec 20, 2013	INCORPORATED	Information incorporated on POH section 8-60
FOL PHE505-013/13	Dec 20, 2013	INCORPORATED	Information incorporated on POH section-9-12-10
FOL PHE505-001/14	Jan 23, 2014	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-002/14	Jan 27, 2014 (Jun 18, 2018)	IN EFFECT	Revision 03

INDEX

FLIGHT OPERATIONS LETTER



User: andreiap0t - Printed by TechPubs - Aug 07/26 - 10:28:19

FOL NUMBER	ISSUED DATE (Revision Date)	FOL STATUS	REMARKS
FOL PHE505-003/14	Jan 31, 2014	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-004/14	Feb 11, 2014	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-005/14	Feb 14, 2014	INCORPORATED	Information incorporated on ACFOG
FOL PHE505-006/14	Feb 10, 2014 (Jun 18, 2018)	INCORPORATED	Information incorporated on POH section 8-30
FOL PHE505-007/14	Feb 10, 2014 (Jun 18, 2018)	IN EFFECT	Revision 04
FOL PHE505-008/14	Feb 10, 2014 (Jun 18, 2018)	INCORPORATED	Information incorporated on POH sections 8-50 and 9-01-75
FOL PHE505-009/14	Feb 21, 2014 (Jun 18, 2018)	IN EFFECT	Revision 01
FOL PHE505-010/14	Apr 11, 2014 (Nov 30, 2022)	INCORPORATED	Information incorporated on QRH
FOL PHE505-011/14	May 20, 2014	CANCELLED	Software update
FOL PHE505-012/14	May 26, 2014	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-013/14	Jun 02, 2014 (Jun 18, 2018)	IN EFFECT	Revision 03
FOL PHE505-014/14	Jul 11, 2014	INCORPORATED	Information incorporated on MEL Guide
FOL PHE505-015/14	Aug 25, 2014	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-016/14	Sep 15, 2014	INCORPORATED	Information incorporated on POH section 8-75
FOL PHE505-017/14	Oct 01, 2014 (Jun 18, 2018)	IN EFFECT	Revision 03
FOL PHE505-018/14	Nov 05, 2014	INCORPORATED	Incorporated on GP-8143
FOL PHE505-019/14	Dec 23, 2014 (Jun 18, 2018)	IN EFFECT	Revision 01

INDEX

FOL NUMBER	ISSUED DATE (Revision Date)	FOL STATUS	REMARKS
FOL PHE505-001/15	Mar 16, 2015	INCORPORATED	Information incorporated on MEL item 21-21-01
FOL PHE505-002/15	Mar 30, 2015	CANCELLED	Information provided by training course
FOL PHE505-003/15	Sep 25, 2015 (Feb 14, 2025)	INCORPORATED	Information incorporated on ACFOG
FOL PHE505-004/15	Dec 21, 2015	CANCELLED	Information provided by IATA Dangerous Goods Regulations
FOL PHE505-001/16	Feb 02, 2016	INCORPORATED	Information incorporated on ACFOG
FOL PHE505-002/16	Feb 22, 2016	INCORPORATED	Information incorporated on TG- 6283 and ACFOG-4438
FOL PHE505-003/16	Feb 17, 2016	INCORPORATED	Information incorporated on POH section 3-70
FOL PHE505-004/16	Jun 06, 2016 (Jun 18, 2018)	INCORPORATED	Information incorporated on TG- 6283 and ACFOG-4438
FOL PHE505-005/16	Jun 06, 2016 (Jun 18, 2018)	IN EFFECT	Revision 03
FOL PHE505-006/16	Jul 01, 2016 (Jun 18, 2018)	IN EFFECT	Revision 03
FOL PHE505-007/16	Jul 05, 2016 (Jun 18, 2018)	IN EFFECT	Revision 01
FOL PHE505-008/16	Aug 12, 2016 (Nov 30, 2022)	IN EFFECT	Revision 02
FOL PHE505-009/16	Sep 02, 2016	CANCELLED	Outdated Information
FOL PHE505-010/16	Sep 09, 2016	CANCELLED	NONE
FOL PHE505-001/18	Aug 06, 2018	IN EFFECT	Original
FOL PHE505-001/19	Jul 31, 2019	IN EFFECT	Original

INDEX

FLIGHT OPERATIONS LETTER



FOL NUMBER	ISSUED DATE (Revision Date)	FOL STATUS	REMARKS
FOL PHE505-002/19	Oct 18, 2019 (Oct 23, 2019)	INCORPORATED	Information incorporated on POH section 9-03-01 and 9-03-10
FOL PHE505-003/19	Oct 23, 2019	IN EFFECT	Original
FOL PHE505-004/19	Nov 29, 2019	IN EFFECT	Original
FOL PHE505-001/20	Feb 04, 2020	IN EFFECT	Original
FOL PHE505-002/20	Mar 03, 2020 (Apr 28, 2026)	IN EFFECT	Revision 02
FOL PHE505-003/20	Apr 15, 2020	IN EFFECT	Original
FOL PHE505-004/20	May 30, 2020	INCORPORATED	Information incorporated on ACFOG section 3-90
FOL PHE505-005/20	Jun 22, 2020 (Feb 14, 2025)	IN EFFECT	Revision 01
FOL PHE505-006/20	Nov 20, 2020	IN EFFECT	Original
FOL PHE505-001/21	Apr 14, 2021 (Nov 30, 2022)	IN EFFECT	Revision 01
FOL PHE505-002/21	May 06, 2021	IN EFFECT	Original
FOL PHE505-001/22	Jan 03, 2022 (Feb 14, 2025)	IN EFFECT	Revision 06
FOL PHE505-002/22	May 09, 2022	IN EFFECT	Original
FOL PHE505-003/22	Dec 05, 2022	CANCELLED	Software update
FOL PHE505-001/23	Apr 05, 2023	INCORPORATED	Information incorporated on ACFOG
FOL PHE505-002/23	May 05, 2023	IN EFFECT	Original
FOL PHE505-003/23	Aug 22, 2023	INCORPORATED	Information incorporated on POH section 4-03-11
FOL PHE505-004/23	Oct 27, 2023	INCORPORATED	Information incorporated on OB 505-001/24

INDEX

FOL NUMBER	ISSUED DATE (Revision Date)	FOL STATUS	REMARKS
FOL PHE505-001/24	Feb 20, 2024 (Feb 14, 2025)	IN EFFECT	Revision 01
FOL PHE505-002/24	Feb 20, 2024	IN EFFECT	Original
FOL PHE505-003/24	Jun 28, 2024	INCORPORATED	Revision of the operational procedure to check the Ram Air Valve actuation of the MEL Guide item 21-21-01
FOL PHE505-001/25	Feb 08, 2025	IN EFFECT	Original
FOL PHE505-001/26	Apr 28, 2026	IN EFFECT	Original
FOL PHE505-002/26	Apr 28, 2026	IN EFFECT	Original
FOL PHE505-003/26	Jul 31, 2026	IN EFFECT	Original

INDEX

INTENTIONALLY BLANK



SUBJECT: SPURIOUS A-I WINGSTB FAIL CAS MESSAGE DURING ENGINE SHUTDOWN IN HOT-WEATHER OPERATIONS

APPLICABILITY: Phenom 300

DESCRIPTION

Embraer has received reports of the A-I WINGSTB FAIL CAS message being spuriously triggered during engine shutdown under hot-weather conditions.

On the ground, when the OAT (Outside Air Temperature) is above 30 °C and the thrust levers are at IDLE, both PRSOVs (Pressure Regulating Shutoff Valves) are commanded to close, resulting in expected no-flow pneumatic condition. However, residual bleed air leakage through the PRSOVs may activate the pressure-relief logic, which in turn commands the Anti-Ice Valves (AIVs) to open.

Under these conditions, some AIV units may remain in a partially open position. If an AIV remains partially open after engine shutdown, a spurious A-I WINGSTB FAIL CAS message may be generated.

RECOMMENDATION

To clear a spurious A-I WINGSTB FAIL CAS message, when OAT is above 30 °C, start the engine and advance the thrust lever angle, ensuring N1 > 50%. This procedure is expected to clear the spurious indication. If the message persists, contact maintenance personnel.

User: andreia0t - Printed by TechPubs - Aug 07/26 - 10:28:19

**FLIGHT
OPERATIONS
LETTER**

DISCLAIMER: This document does not constitute operational approval. If Local Regulatory Authority approval is required, it should be obtained by the Operator.

In case of any conflict between this FOL and any mandatory requirements issued by the Local Regulatory Authority, including but not limited to Airworthiness Directives, the Local Regulatory Authority document/orientation shall prevail.

The information contained herein is proprietary information of Embraer or third parties and shall not be used or disclosed to any third party nor copied or reproduced, whether in whole or in part, in any form or by any means whatsoever without the express written authorization of Embraer. If the reader of this message is not the intended recipient or an agent or employee responsible for delivering it to the intended recipient, you are notified that you have received this document in error, and that any review, dissemination, distribution, or copying of this message is strictly prohibited.

Best Regards,

Flight Operations Support - Executive Jets
Embraer Services & Support
contact.center@embraer.com

User: andreiap0t - Printed by TechPubs - Aug 07/26 - 10:28:19