
Servo Corrections

wrist joint, held to correct angles from

DIt angles



Servo angles

Solve for K:

$$180 = K(-90) + B$$

 $0 = K(+90) + B$

$$180 = K(-90) + B$$

 $0 = -K(+90) - B$
 $180 = -180 K$

Solve for B:

Augle conversion: