

Six Sigma: Week 2

John Fico, Adjunct Professor Fall 2020


MAN 3520 Six Sigma: Fall 2020

Week 2



Agenda: Week 2

- Textbook status update (LS & LSSM texts)
- Download Minitab
- Texas Instruments TI Nspire calculator
 - Will be used to enhance some of the Six Sigma/statistical tools
 - Students do not need to purchase this calculator; will be demonstrated in class
- Finish introduction to defining Six Sigma visually
 - Using Smuckers Uncrustables as example
 - https://www.smuckersuncrustables.com/products/peanut-butter-and-grape-jelly-club-size
- DMAIC principles Quentin Brook Video (our textbook author)
 - Review of project components for each phase
 - https://video.search.yahoo.com/search/video?fr=mcafee&p=what+is+Six+Sigma+DMAIC+video#id=2&vid=62298 1aec8a82e4e62dde0e9dd2fb0a5&action=click
- DMAIC from LS Text Chapters 1-2
 - Review and class discussion
 - What is your impression/interpretation of the different phases?



- Florida Poly Pulse home page
- Finance and Administration
- Technology Services
- Software Downloads
- Minitab





Agenda: Week 2

- (9) class groups have been randomly created (3 students per team)
 - Some assignments will be group-based
- Continue review of DMAIC phases (LS text Chapters 1-2)
 - Review of project components for each phase and class discussion
- Preview of Minitab software (LSSM text)
 - Begin with graphical tools
- Article 1 Discussion Review
 - A few students to provide a brief summary of their assignment in class for discussion

MAN 3520 Six Sigma: Fall 2020

Week 2

3



Six Sigma Defined Visually (cont'd)

Defining Six Sigma visually - Smuckers Uncrustables

https://www.smuckersuncrustables.com/products/peanut-butter-and-grape-jelly-club-size




Identifying & controlling sources of variation in ingredients & baking processes for each sandwich during production are key process variables. y=f(x) Example:

- Y=net sandwich weight
- Xs: How much....
 - jelly?
 - peanut butter?
 - bread?
 - Sandwich dimensions

How much variation is allowed? Determined by customer specifications.

Six Sigma Defined Visually (cont'd)





Initially deployed at Motorola in 1986. Adopted at GE at a global scale in 1990s; inspiring many other companies to follow.

Example: In a 2 Sigma process, 95% of the measured values taken in a process will be within two standard deviations from the process average.

Within in a standard normal distribution:

- 68% of the data points will fall within ± one standard deviation from the mean
- 95% will fall within ± two standard deviations
- 99.73% of the data points will fall within ± three standard deviations from the mean

σ = Standard Deviation




DMAIC vs. DMADV

- Review of DMAIC
- MAN 3520 Course Focus
- Define, Measure, Analyze, Improve, Control
 - Improve existing process (i.e. producing fewer defective parts)
- Review of DMADV
 - Define, Measure, Analyze, Design, Verify)
 - Part of Design for Six Sigma
 - Develop new process (i.e. new product to achieve time to market objective)

Six Sigma projects are characterized by predefined phases – depending on the type of product or process.



DMAIC - Define



- Project scope is clear
- Customer/market value is understood
- Business value is understood
- Process performance measures are agreed upon and baselined
- Business support for project in place (project leader and team)
- Champions & process owners in place to remove barriers

During Define, primary objectives are to understand whether this is the right project and the best project to do right now.

Gaining Understanding of a Process Example: Filing an Income Tax Return





What elements can impact a process?




DMAIC - Define - SIPOC

The Process of Filing Your Tax Return				
S	I	Р	0	С
Suppliers	Inputs	Process	Output	Customers
Government	Forms	Collect Tax Return Information	Completed Tax Return	Government Tax Agency
Employer	Wage Statements	Hire Accountant	Copy for Accountant	Accountant
Charities	Donation Receipts	Review Information with Accountant	Copy for Yourself	
Church	Donation Receipts	File Return	Payment to Accountant	
Investment Firms	Interest Statements	Pay Accountant		

SIPOC is used for understanding the scope and purpose of the process. SIPOC drives important early discussion with the project team about true purpose of process and what it should deliver.



DMAIC - Measure



- Team works to understand current state of process through use of mapping tools
- Focus is on reliability of primary performance metrics
- Once baseline is confirmed, if team finds any quick hits, they can be addressed right away

During Measure, team gets a much deeper understanding of current process; how it has performed in the past and current performance.



DMAIC - Analyze



 Team uses data-drive tools (statistical and/or flow-related to understand key variation sources

The path through the complexities of Measure and Analyze phases is problem specific.

Tools applied depend on the type of problem to be solved.



DMAIC - Improve




- Purpose of Improve is to develop and implement the solution
- Solution is designed based on data and the understanding gained to this point in project
- Ensure that process will achieve its performance goals
- Process is clearly defined and laid out

Once a concept is identified, the team produces a detailed design of the improved process and pilots the design to ensure success.



DMAIC - Control




- Process control mechanisms are in place
- Process is executed consistently
- Process performance meets project goals and is sustainable
- Process staff is set at appropriate competency level

The primary deliverable of any project is the Control Plan, which represents all of the elements that must come together to ensure the process is sustainable.

Measure: Types of Data (Data Worlds)






Measure: Types of Data (Data Worlds)

Measure - Overview



The Measure phase aims to set a stake in the ground in terms of process performance (a baseline) through the development of clear and meaningful measurement systems.

The flow through Measure:



Don't be tempted to jump ahead to root causes (Analyse) or solutions (Improve) until the process can be measured effectively. The Measure phase builds upon the existing data available (introducing new data collection and measurements if necessary) in order to fully understand the historical behaviour of the process. Team members on their first Six Sigma project often find the Measure phase surprisingly detailed and rigorous but, with experience, realise that it is a worthwhile investment that always pays off later in the project.

MEASURE > Overview


34

Summarizing Process Data



Statistics for Summarising Process Position

It is more than likely that your chosen KPIs involve an 'average' of some kind. Despite the common use of the arithmetic average, it is worth remembering that there are alternatives!



The two key features of a histogram are its central Position and its Spread:

The **Spread** of the histogram (how wide it is) is important because it gives an indication of the amount of variation in the process. This is explained further on the next page.


The **Position** of the histogram refers to where the process is centred. There are two common statistics that can be used to reflect Position:

- 1) The Average commonly used because it is easy to understand and calculate. The average works well where the process is reasonably symmetrical and there are not any 'outliers' (unexpectedly small or large data points) which can significantly affect the calculation of the average.
- 2) The Median less widely used, but a useful statistic due to its 'robustness'. The median is defined as the middle value of the data (the 50th percentile) and its calculation is not significantly affected by any outliers in the data.

Alternative terminology for the average:

- Mean sometimes used instead of average.
- X̄ (pronounced 'X Bar') used to represent the average of a sample.
- μ (pronounced 'mu') used to represent the average of the total population.

NB: In theory, X Bar and Mu are for use in the different situations described above. In reality, they're often used interchangeably (although this isn't very good statistical practice).



MEASURE > Statistics for Process Position

Summarizing Process Data


FLORIDA POLYTECHNIC

MEASURE > Statistics for Process Spread

41

Statistics for Summarising Process Spread

Six Sigma focuses on reducing process variation and so a measurement for variation is essential.




Standard Deviation = 3

Range = 15

The Spread of the histogram indicates the amount of variation in the process. There are two alternative statistics that can be used to measure variation:

support its use both in a training environment and

- 1) Range commonly used because it is easy to understand. The range is the difference between the maximum and minimum results, and because of this 'simple' approach it is not very robust. Just one outlier in the process will increase the range dramatically.
- 2) Standard Deviation is a more robust measure of variation, but it is perceived as difficult to understand because it is not easy to picture what it is. See below for an explanation.




A practical definition of Standard Deviation is:

> "The average distance of the data points from their own average".

The distance of the data points from their own average is shown graphically here by the blue dotted lines on the Time Series plot.

The symbol used for standard deviation is the Greek symbol ' T' - pronounced Sigma!



Distributions.mpj This data file contains a selection of the different distributions shown over the last two pages.

Six Sigm:



Measure: Six Sigma Tools

- Key Performance Indicators (KPIs) pages 34-35
- Summarizing Process Data (Position and Spread) pages 40-41
- Types of Data (Data Worlds) page 45
- Minitab[®] Graphical tools to cover (LSSM text)
 - Summary of graphical tools (page 118)
 - Histograms (page 123)
 - Graphical Summary (page 126)
 - Pareto Analysis (page 136)
 - Time Series Plots (page 130)
 - Dot Plots (page 125)
 - Scatter Plots (page 145)
 - Box Plots (page 140)
 - Fitted Line Plots (page 198)

Demonstration of Six Sigma analysis tools in Minitab during course

Problem Solvers Guide



