


Turn in	Allowable tolerance = $\pm 5\%$	
1) Assembly (Use configuration "With Gears") Use "Pack and Go" Command to save assembly	Mass = 7.20 pounds	7.3
Part Worm Gear Shaft should be oriented as shown with the hex end pointing toward the positive z direction, see below. (Don't worry about part colors)	Volume = 27.17 cubic inches	27.3?
Part Offset shaft Gear should be oriented as shown with the hexagonal end pointing toward the positive x direction, see below. (Don't worry about part colors)	Center of mass: (inches) X = 0.01 Y = 1.88 Z = 0.01	1.9



2) Exploded view in your Assembly (should look like the picture below and on pg. 630)

