

Lab 2 Assembling and Calibrating the PiDog

Mahdi Muhamadkhani | ITAI 2374 | September 23, 2026

Session Overview

This was our group's first session working with the PiDog kit. We focused on unpacking the components and completing the first assembly steps. The work described here covers initial assembly and setup; servo calibration remains for a later stage.

My Participation and Group Work

I helped unpack the kit and organize the components, screws, and brackets. We examined the parts to determine which screws and mounting pieces were needed before putting them together. Working as a group, we assembled the metal frame, attached the upper mounting piece and white bracket, and used screws to secure the main board and supporting structure.

We also connected cables during setup. Our group's activities included installing the battery and heatsink and powering on the unit. Members contributed to different steps, making this a shared assembly effort. The photographs below document parts preparation and work on the assembly.

Learning and Next Steps

This session gave me practice organizing hardware and working with others through an unfamiliar assembly process. Some cable functions still need to be checked against the official instructions rather than identified by color alone. Next, we need to verify the mounting and wiring, continue assembly, and complete the official calibration routine for all 12 servos. Neutral-position checks and movement testing remain to be completed.

Lab Photographs



Left: Group preparation with kit components. Right: Securing parts during assembly.

Assembly reference: [SunFounder PiDog documentation](#)