Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
0520	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	150 hour checks carried out	Line	Performed	B1	S0009828 4167825	08/03/2018	0.3	Anthony Mutch UK.66.50413 3C
0520	ZM517 / G-CJZT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine magnetic plugs visual inspection carried out IAW MSM 05-20-1-201-830-A01	Line	Performed	B1	S0011405 4180945	12/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
0520	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the ELT system carried out IAW 05-25-10, 6-1	Base	Performed	B1	S0012711	18/09/2018	0.1	Gary Smith B2 UK.66.45833 7K
0520	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Functional Test of ELT system carried out IAW 05-25-10, 6-1	Base	Performed	B1	S0012711 4192909	18/09/2018	0.1	Gary Smith B2 UK.66.45833 7K
0520	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	12 Month inspection carried out IAW MSM 05-23-10, 6-1	Base	Performed	B1	S0012711 4192925	18/09/2018	0.1	Scott Gibbs UK.66.48241 2A
0550	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspections post VNE excedance carried out IAW MSM 05-51-10, 6-20	Base	Performed	B1	S0009940 4168619	05/02/2018	0.3	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
0550	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspections post Overspeed carried out IAW MSM 05-51-10, 6-7	Base	Performed	B1	S0009940 4168619	05/02/2018	0.3	Scott Gibbs UK.66.48241 2A
0550	ZM510 / G-CJUA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Heavy Landing checks carried out post tail strike, IAW MSM 05-51-10, 6-1	Line	Performed	B1	S0011590 4182333	08/06/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
0550	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Heavy landing checks carried out IAW MSM 05-51-10, 6-3	Base	Performed	B1	S0012479	21/08/2018	0.3	Scott Gibbs UK.66.48241 2A
0700	ZM517 / G-CJZT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Lifting helicopter Via Crane IAW AMM 07-00-00, 2-1	Line	Performed	B1	S0009685 4166425	13/02/2018	0.4	Ken Grant UK.66.42002 3C
0710	G-CKVH	EUROCOPTER	AS 350 B3	Turbomeca Arriel 2	2b	Aircraft jacked IAW AMM 07-10-00-3-1	Base	Performed	B1	GP.510051 .C.3.0002 4196969	12/09/2018	0.3	David Spiers UK.66.45617 6G
0720	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aircraft shored for transmission removal, IAW AMM, 07-50-01, 2-1	Base	Performed	B1	S0012479	21/08/2018	0.1	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
0800	G-CKVH	EUROCOPTER	AS 350 B3	Turbomeca Arriel 2	2b	Aircraft levelled for weigh IAW AMM 08-20-00,3-1	Base	Performed	B1	GP.510051 .C.3.0002 4196969	12/09/2018	0.3	David Spiers UK.66.45617 6G
0810	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Weight and balance temporary amendment carried out for crew seat move. IAW FLM section 6.1	Line	Performed	B1	SRP 000829	17/05/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
0810	G-CKVH	EUROCOPTER	AS 350 B3	Turbomeca Arriel 2	2b	Aircraft weighed post modification IAW AMM 08-10-00-3-1	Base	Performed	B1	GP.510051 .C.3.0002 4196969	12/09/2018	0.1	David Spiers UK.66.45617 6G
0900	ZM510 / G-CJUA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aircraft moved from hangar to line IAW AMM 09-10-00, 2-1	Line	Performed	B1	N/A	20/02/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
0900	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Aircraft moved from flight line to hangar maintenance dock IAW AMM 09-10-00, 2-1	Line	Performed	B1	N/A	20/02/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
0900	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Ground handling wheels fitted for moving of aircraft IAW AMM 09-10-00, 4-1	Line	Performed	B1	SRP 011802	27/09/2018	0.1	Paul Wilkinson UK.66.41982 24

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
1010	ZM519 / G-CKEU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aircraft placed into storage preservation IAW AMM 10-10-00, 2-2	Base	Performed	B1	4178390 S0011099	10/05/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
1021	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor blades tied down for high winds IAW AMM 10-10-00, 2-3	Line	Performed	B1	N/A	13/02/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
1100	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Check of livery decals and aircraft placards/Markings IAW AMM 11-00-00, 2-1 and A/H Drawing N°AHUK/135/3099	Base	Performed	B1	S0010996 4177640	08/06/2018	0.3	Scott Gibbs UK.66.48241 2A
1200	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	15H/7Day Check carried out IAW AMM 12-11-00, 3-16	Line	Performed	B1	S0009200	11/01/2018	0.1	James R Bramwell UK.66.45490 8B
1200	ZM527 / G-CKOB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine Oil level check and replenish, carried out IAW AMM 12-10-00, 3-2	Line	Performed	B1	SRP 002665	24/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
1200	ZM527 / G-CKOB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Daily pre-flight check carried out IAW MPW-F-214 and MSM 05-21-10, 6-1	Line	Performed	B1	SRP 002665	24/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
1200	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aircraft places in to preservation S0022494	Line	Performed, Supervised, Released	B1	N/A	29/06/2020	0.3	Clarke
1210	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Rotors running refuel carried out. IAW AMM 12-10-00, 3-1	Line	Performed	B1	N/A	20/02/2018	0.1	Michael Henderson UK.66.47642 1H
1210	ZM514 / G-CJXV	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aircraft refuelled IAW AMM 28-10-00, 3-1	Line	Performed	B1	S0012001 4186084	06/07/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
1230	ZM514 / G-CJXV	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aircraft fuel tanks defueled. IAW AMM 12-30-00, 3-3	Line	Performed	B1	S0012001 4186084	06/07/2018	0.3	Christopher Bray B1.3 LAE UK.66.49865 2L
1810	G-CPAO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Tracking/Adjust main rotorhead IAW AMM 18-10-00, 5-1	Base	Performed	B1	S0005368 4122202	25/11/2016	0.3	Daniel Hazell UK.66.47741 3B
1810	ZM525 / C-CKJX	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Track and Balance carried out post blade repair IAW 18-11-00, 5-1 IAW 18-11-00, 5-2	Line	Performed, Supervised, Released	B1	N/A	16/10/2019	0.5	Matthew Clarke UK.66.52289 0E

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2000	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Produce for spectral oil analysis program IAW Standard Practices Manual(SPM) 20-00-00,2-24	Line	Performed	B1	S0009758 4167181	09/02/2018	0.1	Andrew Patty UK.66.47246 6F
2000	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Overhead panel connecter pin extracted IAW SPM 20-80-20-101	Base	Performed	B1	S0009794 4167390	27/02/2018	0.3	Johnathan Hughes B2 CAA AML/419917L
2000	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Overhead light flow panel wire soldered IAW SPM 20-80-20-102.	Base	Performed	B1	S0009794 4167390	27/02/2018	0.3	Johnathan Hughes B2 CAA AML/419917L
2000	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Co-pilot Force trim release switch cleaned and lubricated IAW SPM 20-04-01-102	Line	Performed	B1	S0011822 4184365	23/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
2000	G-ETPF	EUROCOPTER	AS 350 B	Turbomeca Arriel 1	2b	Rivets installed as part of SB 29.00.03 IAW SPM 20-03-02-401	Base	Performed	B1	GP.510058 .R4.ETPF 4193207	30/08/2018	0.3	Andy Bryant AML/421755A
2000	G-ETPF	EUROCOPTER	AS 350 B	Turbomeca Arriel 1	2b	Rivets removed for embodiment of SB 29.00.03 IAW SPM 20-03-01-102	Base	Performed	B1	GP.510058 .R4.ETPF 4193207	30/08/2018	0.3	Andy Bryant AML/421755A
2000	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Termination and crimping of wires during modification. IAW SPM 20-80-20-425 and 20-80-20-408	Base	Performed	B1/B2	S0012743 1009308	09/09/2018	0.3	Arthur G Clyne UK.66.44662 5K

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2000	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Cables stripped IAW SPM 20-80-20-407	Base	Performed	B1/B2	S0012743 1009308	09/09/2018	0.3	Arthur G Clyne UK.66.44662 5K
2000	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Insert and extract of electrical connector pin IAW SPM 20-80-20-101	Base	Performed	B1/B2	S0012743 1009308	10/09/2018	0.3	Arthur G Clyne UK.66.44662 5K
2000	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Removal and installation of cable ties IAW SPM 20-80-20-402 S0012743 1009308	Base	Performed	B1/B2	S0012743 1009308	10/09/2018	0.4	Arthur G Clyne UK.66.44662 5K
2000	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Installation of relay and module blocks IAW SPM 20-80-20-413	Base	Performed	B1/B2	S0012743 1009308	10/09/2018	0.1	Arthur G Clyne UK.66.44662 5K
2100	ZM526 / G-CKOC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	During power up checks, hot air mixing unit motors heard to continuously motor, Wiring diagram manual (WDM) 21-40-00-000 consulted and heating control switch potentiometer module changed IAW AMM 24-62-02, 8-2 as part of fault diagnosis using fault charts IAW AMM 21-00-00, 1-1 Mixing unit motor continues to motor, Mixing unit internal fault of limit switch suspected, Mixing Unit changed IAW AMM 21-40-00, 4-5	Line	Performed	B1	S0011931	25/06/2018	0.3	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2122	ZM512 / G-CJXS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fwd R/H Subfloor heating hoses installed IAW AMM 21-22-00, 4-9	Base	Performed	B1	S0011234 4179705 2	30/05/2018	0.1	Scott Gibbs UK.66.48241 2A
2140	ZM526 / G-CKOC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Hot air Mixing Unit changed IAW AMM 21-40-00, 4-5	Line	Performed	B1	S0011931	25/06/2018	0.3	Christopher Bray B1.3 LAE UK.66.49865 2L
2200	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Ground run and Pre Flight AFCS tests carried out. IAW FLM 4.4.1.3	Line	Performed	B1	S0010198 4170601	15/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
2200	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	AFCS fails pre-flight test, fault diagnosis carried out and collective trim actuator suspect at fault, collective trim actuator replaced and functional check and pre-flight check carried out, both test still fail. during further inspections, co-pilot force trim release switch found to be sticking intermittently. switch cleaned and lubricated. functional test and pre-flight check carried out, both passed. original collective trim actuator refitted. S0011822 4184365	Line	Performed	B1	N/A	23/06/2018	0.8	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2212	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Pitch roll computer replaced IAW AMM 22-12-00,4-1	Line	Performed	B1	S00010198 4170601	15/03/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
2212	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fault Diagnoses "AP Fail x 3" SAS 2000 Computer replaced IAW AMM 22-12-00, 4-1 for Fault Diagnoses. Ground Run carried out with maintenance test pilot IAW FLM 4.4.1.3 test passed. Original SAS 2000 Computer found to be faulty.	Line	Performed	B1	S00010198 4170621	15/03/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
2300	ZM527 / G-CKOB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Unable to transmit on UHF channels. During fault diagnosis, forward and rear Audio Control Units(ACU) unable to communicate. Remote Electronic Unit (REU) checked as part of fault diagnosis, no fault found, During fault diagnosis R/H passengers ACU removed IAW AVM 23.41.39, remaining ACU's found to function correctly during functional test IAW AVM 23.41.39, R/H ACU found to be at fault.	Base	Performed	B1	S0011948 4185662	27/06/2018	0.1	Johnathan Hughes B2 CAA AML/419917L
2312	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Funcational test of aircraft VHF system carried out IAW AVM 23-14-07	Line	Performed	B1	S0009684 4166413	31/07/2018	0.1	Donald G Parker UK.66.41649 1A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2327	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Functional test of TCAS carried out IAW AVM 23-27-05	Line	Performed	B1	S0012411 4189506	31/07/2018	0.1	Donald G Parker UK.66.41649 1A
2341	ZM527 / G-CKOB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Audio control unit replaced IAW AVM 23.41.39	Line	Performed	B1/B2	S0011948 4185662	27/06/2018	0.1	Johnathan Hughes B2 CAA AML/419917L
2341	ZM527 / G-CKOB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Audio control unit functional test carried out IAW AVM 23.41.39	Line	Performed	B1/B2	S0011948 4185662	27/06/2018	0.1	Johnathan Hughes B2 CAA AML/419917L
2341	ZM527 / G-CKOB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Functional check of remote electronic unit carried out IAW AVM 23-41-38	Line	Performed	B1/B2	S0011948 4185662	27/06/2018	0.1	Johnathan Hughes B2 CAA AML/419917L
2400	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Cycle Circuit breakers IAW CAP 562 CAAIP B-180-AP 24-4	Base	Performed	B1	S0006886	15/09/2017	0.1	Christopher Wright B2 LAE UK.66.49216 6F
2400	ZM507 / G-CJRP	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Power ON/OFF IAW AMM 24-00-00, 2-1	Line	Performed	B1	S0009210	10/01/2018	0.1	Michael Henderson UK.66.47642 1H

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2430	G-PSNO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 C2 Series	Turbomeca Arriel 1	1	Inspect of Starter generator IAW AMM 24-30-00, 6-1	Base	Performed	B1	4123541	10/02/2017	0.3	William Morris UK.66.50145 4J
2430	G-PSNO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 C2 Series	Turbomeca Arriel 1	1	Starter Generator Removal IAW AMM 24-30-00, 4-2	Base	Performed	B1	4123541	10/02/2017	0.3	William Morris UK.66.50145 4J
2430	ZM507 / G-CJRP	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Battery Change IAW AMM 24-30-00, 4-1	Line	Performed	B1	S0009210	10/01/2018	0.1	Michael Henderson UK.66.47642 1H
2430	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Starter/Generator installed IAW AMM 24-30-00,4-2	Base	Performed	B1	s0008536 4155560 Task 3	01/03/2018	0.1	Scott Gibbs UK.66.48241 2A
2433	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Emergency power supply battery replaced IAW AMM 24-33-00,4-2 S0015061 4215930	Line	Performed	B1	N/A	17/01/2019	0.1	Anthony Mutch UK.66.50413 3C
2433	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Functional check of standby battery carried out IAW AMM 24-33-00, 5-4 S0015061 4215930	Line	Performed	B1	N/A	17/01/2019	0.1	Anthony Mutch UK.66.50413 3C

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2440	ZM507 / G-CJRP	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Ground power notification fails to iluminate with GPU panel open. Fault diagnoses carried out and GPU door micro switch found to be inoprative. Micro swtich replaced IAW TE-2018-EC135-02099	Line	Performed	B1	S0012750 4192749	20/08/2018	0.3	Michael Henderson UK.66.47642 1H
2460	ZM526 / G-CKOC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	heating control switch potentiometer module changed IAW AMM 24-62-02, 8-2	Line	Performed	B1	S0011931	25/06/2018	0.2	Christopher Bray B1.3 LAE UK.66.49865 2L
2500	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Hoist Limit Switch Assy, Functional Check IAW Hoist CMM 25-00-21-1	Line	Performed	B1	S0009201	11/01/2018	0.1	James R Bramwell UK.66.45490 8B
2500	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Hoist Dimensional Check IAW Hoist CMM 25-00-21-1	Line	Performed	B1	S0009201	11/01/2018	0.1	James R Bramwell UK.66.45490 8B
2500	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Clean and Lubrication of Hoist Cable IAW Hoist CMM 25-00-21-1	Line	Performed	B1	S0009201	11/01/2018	0.1	James R Bramwell UK.66.45490 8B
2500	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Hoist hook Retaining Ring check carried out IAW Hoist CMM 25-00-21-2	Line	Performed	B1	S0009201	11/01/2018	0.1	James R Bramwell UK.66.45490 8B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2500	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Dimension of hoist hook damper assy lock system IAW Hoist CMM 25-00-21-1	Line	Performed	B1	S0009201	11/01/2018	0.1	James R Bramwell UK.66.45490 8B
2500	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Monthly damper check, Goodrich Hook Damper IAW Hoist CMM 25-00-29-1	Line	Performed	B1	S0009201	11/01/2018	0.1	James R Bramwell UK.66.45490 8B
2500	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection for correct contents and expiry date carried out on medical box S0014514 4211191	Base	Performed	B1	N/A	09/01/2019	0.1	Becky Smith UK.66.50528 7D
2511	ZM521 / G-CKIK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Pilots seat removed from ZM521 IAW AMM 25-11-00,4-1	Line	Performed	B1	S0010197 SAP 4170947 Tsk 5	19/04/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
2511	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Pilots seat installed to ZM511 IAW AMM 25-11-00,4-1	Line	Performed	B1	S0010738 SAP 4175538 Tsk 4	19/04/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
2511	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Pilots seat removed and fitted for access IAW AMM 25-12-00, 4-1	Line	Performed	B1	N/A	17/01/2019	0.1	Anthony Mutch UK.66.50413 3C

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2520	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Remove Front roof panel IAW AMM 25-20-00, 4-1	Base	Performed	B1	S0006886	08/09/2017	0.1	Richard Buckle UK.66.49191 6E
2520	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Remove rear Cargo panel IAW AMM 25-20-00, 4-2	Base	Performed	B1	S0006886	08/09/2017	0.1	Richard Buckle UK.66.49191 6E
2520	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Remove cargo compartment panel IAW AMM 25-20-00, 4-2	Base	Performed	B1	S0006886	08/09/2017	0.1	Richard Buckle UK.66.49191 6E
2520	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Remove Side Channel Covers IAW AMM 25-50-00 4-3	Base	Performed	B1	S0006886	08/09/2017	0.1	Richard Buckle UK.66.49191 6E
2520	ZM507 / G-CJRP	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Interior trim fitted IAW AMM 25-20-00, 4-3	Base	Performed	B1	S0010202 SAP 4170711	17/04/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
2522	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Utility Seat Bench removed and fitted IAW AMM 25-21-02,4-1	Line	Performed	B1	SRP 000340	13/03/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2522	ZM523 / G-CKJW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Crew seat removed stud 19 and fitted to 41 for configuration change IAW AMM 25-11-00, 4-1	Line	Performed	B1	SRP 0007542	13/03/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
2610	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	engine fire warning inspect carried out IAW AMM 26-10-00, 6-1	Base	Performed	B1	S0006884 4147368	15/09/2017	0.1	Christopher Wright B2 LAE UK.66.49216 6F
2621	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the engine fire extinguishing system carried out IAW AMM 26-21-00, 6-1	Base	Performed	B1	S0012711 4192925	18/09/2018	0.3	Michael Gillet UK.66.47942 2B
2621	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Explosive Cartridges for Fire Extinguishing Bottle removed and fitted IAW AMM 26-21-01, 4-4 S0014326 4209782	Line	Performed	B1	N/A	30/11/2018	0.1	Michael Gillett UK.66.47942 2B
2621	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fire Extinguishing Bottle determination of Weight carried out IAW AMM 26-21-01, 5-1 S0014326 4209782	Line	Performed	B1	N/A	30/11/2018	0.1	Michael Gillett UK.66.47942 2B
2621	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fire extinguishing bottle removed and fitted IAW AMM 26-21-01,4-1 S0014326 4209782	Line	Performed	B1	N/A	30/11/2018	0.3	Michael Gillett UK.66.47942 2B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2623	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Baggage bay fire extinguisher squib replaced IAW AMM 26-23-01-063	Base	Performed	B1	S0008863 4161372 Task 24	25/01/2018	0.3	Matthew Hynes UK.66.43630 9D
2811	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	During Aircraft Start Amber "Aft Fuel Pump" Caption noted and Aft Transfer pump CB Popped Motor Pump cartridge replaced IAW 28-11-01-8-2 Functional Check carried out IAW 28-10-00, 5-2 S0019518 4263574	Line	Performed, Supervised, Released	B1	N/A	20/11/2019	0.8	Matthew Clarke UK.66.52289 0E
2840	ZM514 / G-CJXV	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fuel system leak check carried out post defuel IAW AMM 28-40-00, 5-2	Line	Performed	B1	S0012001 4186084	06/07/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
2840	ZM514 / G-CJXV	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fuel System Indication, Test of display accuracy carried out IAW AMM 28-40-00, 5-3	Line	Performed	B1	S0012001 4186084	06/07/2018	0.3	Christopher Bray B1.3 LAE UK.66.49865 2L
2840	ZM514 / G-CJXV	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fuel monitoring and fuel quantity indication, Functional test of low level warning carried out IAW AMM 25-40-00, 5-2	Line	Performed	B1	S0012001 4186084	06/07/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2840	ZM508 / G-CJRY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fuel Qty Fail & Intermittant fuel reserve on master list. Fuel Sensor Removed/ Fitted 28-40-00, 4-1 Fuel Sensor Cleaned and drying out carried out 24-40-00, 7-1 Fuel Sensor quantity Functional Test Carried out 28/40/00, 5-4 S0017592	Line	Performed, Supervised, Released	B1	N/A	10/07/2019	0.4	Matthew Clarke UK.66.522890E
2900	ZM509 / G-CJTZ	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Perform pressure test of hydraulic power system carried out IAW AMM 29-00-00, 5-2	Line	Performed	B1	S00059414164115	18/01/2018	0.3	Christopher Bray B1.3 LAE UK.66.498652L
2900	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	External pump drives connected and disconnected IAW AMM 29-00-00, 2-1	Base	Performed	B1	S00085364155563	27/02/2018	0.3	Scott Gibbs UK.66.482412A
2900	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Hydraulic power applied using external pump drives IAW AMM 29-00-00, 2-1	Line	Performed	B1	S00118224184365	23/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.498652L
2900	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Hydraulic Power System inspection carried out IAW AMM 29-00-00, 6-1	Line	Performed	B1	S0012479	22/08/2018	0.3	Scott Gibbs UK.66.482412A
2900	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of hydraulic pumps, reservoirs and valve blocks carried out IAW AMM 29-00-00, 6-1	Base	Performed	B1	S00127114192924	18/09/2018	0.1	Michael Gillet UK.66.479422B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
2900	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Hydraulic system replenished IAW AMM 29-00-00, 3-1	Base	Performed	B1	S0012711 4192925	18/09/2018	0.1	Michael Gillet UK.66.47942 2B
2900	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Hydraulic system bleed carried out IAW AMM 29-00-00, 3-2	Base	Performed	B1	S0012711 4192925	18/09/2018	0.1	Michael Gillet UK.66.47942 2B
2900	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Hydraulic system leak check carried out IAW AMM 29-00-00, 5-1	Base	Performed	B1	S0012711 4192925	18/09/2018	0.1	Michael Gillet UK.66.47942 2B
2900	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main hydraulic filter changed IAW AMM 29-12-00, 8-3	Base	Performed	B1	S0012711 4192925	18/09/2018	0.3	Michael Gillet UK.66.47942 2B
2900	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Lubrication of splines or the hydraulic pump drive shaft IAW AMM 29-00-00, 3-4 S0014514 4211179	Base	Performed	B1	N/A	09/01/2019	0.1	Becky Smith UK.66.50528 7D
2910	G-RIDA	EUROCOPTER	AS 355 NP	Turbomeca Arrius 1	1	Accumulator check of inflation pressure, Inflation/deflation of trim tab accumulated - Twin Hydraulic System IAW AMM 29-10-20-302	Base	Performed	B1	M028009 4143541	27/07/2017	0.1	Craig Wilson CAA. AML/ 421889B
2910	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	hydraulic pressure supply system removed and installed IAW AMM 29-10-00, 4-1 S0014514 4211191	Base	Performed	B1	N/A	09/01/2019	0.3	Becky Smith UK.66.50528 7D

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
3040	ZM519 / G-CKEU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Embodiment of SB135-30-001 Windscreen Wiper system motor and Gearbox upgrade. S0017137	Line	Performed, Supervised, Released	B1	N/A	10/06/2019	0.5	Matthew Clarke UK.66.522890E
3042	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of Windshield wiper carried out IAW AMM 30-42-00, 6-1	Base	Performed	B1	S0008536 4155563 °7	01/03/2018	0.1	Scott Gibbs UK.66.482412A
3042	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Wiper blade found to be outside of parked area. Wiper blade adjusted IAW AMM 30-42-00,5-2	Base	Performed	B1	S0008536 4169237 °27	01/03/2018	0.1	Scott Gibbs UK.66.482412A
3042	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Windscreen wiper found locked fully to the L/H side. Fault diagnoses carried out, Via functional test IAW AMM 30-42-00, 5-1, Wiper motor fails to operate, during inspection of wiper motor, IAW AMM 30-42-00, 6-1 wiper pivot arm link found detached causing motor to actuate but wiper to not operate.	Line	Performed	B1	S0010944 4177130	29/04/2018	0.3	Christopher Bray B1.3 LAE UK.66.498652L
3042	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Windscreen wiper functional check carried out IAW AMM 30-42-00, 5-1	Line	Performed	B1	S0010944 4177130	29/04/2018	0.1	Christopher Bray B1.3 LAE UK.66.498652L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
3042	ZM515 - G-CJSO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Windscreen Wiper blade range incorrect,. Fault diagnosis carried out IAW AMM 30-42-00,1-1 Wiper arm removed and fitted IAW 30-42-00,8-1 Windscreen Wiper system gearbox removed and fitted IAW 30-42-00,4-1 Motor crank arm set to correct position IAW 30-42-00,8-4 Windscreen Wiper system functional check carried out IAW 30-42-00, 5-1 S0015215 4217153	Line	Performed	B1	N/A	24/01/2019	0.1	Michael Gillett UK.66.47942 2B
3100	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	"Download Fail" Caption on Vehicle Monitoring System (VMS). VMS/UMS Downloaded to Flash card IAW FLM 08-06-01	Line	Performed	B1	SRP 000484	12/03/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
3131	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Flight Data Recording system (FDRS) warning indicated on Multi Function Display (MFD) during start up. Fault diagnosis carried out and rear FDRS inertia switch found to have been inadvertently activated. Switch reset IAW AMM 31-32-10, 5-6	Line	Performed	B1	SRP00044 4	19/01/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
3160	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Functional test of EuroNav system carried out IAW AVM 31-68-07	Line	Performed	B1	S0012411 4189506	31/07/2018	0.1	Donald G Parker UK.66.41649 1A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
3210	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Main Landing gear Microswitch Servicing IAW AMM 32-10-00-611	Base	Performed	B1	S0008863 4161673	23/01/2018	0.1	Matthew Hynes UK.66.43630 9D
3210	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main landing gear crosstube inspection carries out IAW AMM 32-10-01, 6-1	Base	Performed	B1	S0011893 4184731	16/08/2018	0.1	Scott Gibbs UK.66.48241 2A
3210	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	landing gear removed and fitted IAW AMM 32-10-00, 4-1	Line	Performed	B1	S0009685 4166425	18/08/2018	0.3	Michael Gillet UK.66.47942 2B
3210	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the grounding strips of the main undercarriage carried out IAW 32-10-01, 6-1 S0014514 4211191	Base	Performed	B1	N/A	09/01/2019	0.2	Becky Smith UK.66.50528 7D
3210	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Undercarriage skids replaced. RE role from marine fit to land role	Line	Performed, Supervised, Released	B1	N/A	21/08/2020	1	Christopher Bray B1.3 LAE UK.66.49865 2L
3220	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Nose landing gear microswitch Servicing IAW AMM 32-20-00-611	Base	Performed	B1	S0008863 4161673	23/01/2018	0.1	Matthew Hynes UK.66.43630 9D

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
3270	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Inspection of tail skid support assembly carried out IAW AMM 32-70-01-221	Base	Performed	B1	S0008863 4161673	23/01/2018	0.3	Matthew Hynes UK.66.43630 9D
3270	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Tail Skid removed and fitted IAW AMM 32-70-01-061	Base	Performed	B1	S0008863 4161673	23/01/2018	0.5	Matthew Hynes UK.66.43630 9D
3321	ZM507 / G-CJRP	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Cargo light functional check post trim fitting carried out IAW AMM 33-21-00,5-1	Base	Performed	B1	WO S0010202 SAP41707 11	17/04/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
3341	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Rear white position light Removed and Fit IAW AMM 33-41-00, 4-1	Base	Performed	B1	S0006886 4148165	15/09/2017	0.1	Christopher Wright B2 LAE UK.66.49216 6F
3341	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Red position LED inoperative. Volts check and ground check carried out for fault diagnosis, IAW AMM 33-41-00, 6-1 No faults apparent. Suspect LED position light internal fault.	Line	Performed	B1	s0011668 4182977	15/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
3343	ZM509 / G-CJTZ	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Post co-pilots collective level fit, functional check of search light carried out IAW AMM, 33-43-20, 5-1	Line	Performed	B1	S0011660 4182955	13/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
3343	ZM509 / G-CJTZ	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Post co-pilot collective lever fitment functional check of landing light carried out IAW AMM 33-43-00, 5-2	Line	Performed	B1	S0011660 4182955	13/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
3343	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Nose landing light inoperative, Lamp replaced IAW AMM 33-43-00,4-1	Line	Performed	B1	S0011667 4182975	13/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
3345	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Infra Red flood light fitted IAW Supplementary Maintenance Manual (SAMM) 33-45-00, 4-1	Line	Performed	B1	S0010922 4177056	29/04/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
3345	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Function Test of Infra Red Flood light carried out IAW SAMM 33-45-00, 5-1	Base	Performed	B1	S0010922 4177056	29/04/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
3411	ZM507 / G-CJRP	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Leakage test of pitot-static system carried out IAW AMM 34-11-00, 5-1	Base	Performed	B1	S0010202 SAP 4170694 Task 21	13/04/2018	0.1	Jonhathan Hughes B2 CAA AML/419917L
3415	ZM507 / G-CJRP	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Display accuracy of the pitot-static system check carried out IAW AMM 34-15-00, 5-2 and 34-27-00, 5-2	Base	Performed	B1	S0010202 SAP 4170694 Task 22	13/04/2018	0.1	Johnathan Hughes B2 CAA AML/419917L
3422	ZM512 / G-CJXS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	N°1 Attitude Heading Reference System unit Installed IAW AMM 34-22-00, 4-1	Base	Performed	B1	S0011234 4179720	30/05/2018	0.3	Johnathan Hughes B2 CAA AML/419917L
3422	ZM512 / G-CJXS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	N°1 Attitude heading reference system Functional check carried out IAW AMM 34-22-00, 5-1	Base	Performed	B1	S0011234 4179720	30/05/2018	0.1	Johnathan Hughes B2 CAA AML/419917L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
3458	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Navigation Managment System (NMS), GPS GTN750 terrain update not completing. "DATA BASE NOT LOADED" warning displayed on NMS screen. NMS 1 and 2 Transposed IAW AMM 34-63-00, 4-1 fault still apparent. Garmin subscription updated and test carried out, Fault still apparent. Garmin card 1 and 2 transposed, fault cleared, Fault found to be that subscription on Garmin card a specific to each NMS module. IAW Avionic Maintenance Manual (AVM) 34-63-12	Line	Performed	B1	S0011884 4184629	24/06/2018	0.4	Christopher Bray B1.3 LAE UK.66.49865 2L
3460	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Functional test of VHF1 System Carried out IAW AVM Chap 34-63-12	Line	Performed	B1	S0012130 4187260	31/07/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
3462	ZM511 / G-CJUC	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Navigation management system 1 and 2 Transposed IAW AMM 34-63-00, 4-1	Line	Performed	B1	S0011884 4184629	24/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
4600	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aircraft started in Helionix maintenance mode for flight data download IAW AMM 46-00-00 5-2	Base	Performed	B1	S0009940 4168619	01/03/2018	0.1	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
5120	ZM512 / G-CJXS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Anchor screw insert fitted IAW SRM 51-20-00, 8-18	Line	Performed	B1	S0011234 4179705	26/05/2018	0.3	Christopher Bray B1.3 LAE UK.66.49865 2L
5170	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Clam shell door composite repair carried out IAW RDAS AIRF-001/2019, E-repair manual 51-71-52,8-3 and 51-71-52,8-5 S0014630 4211815	Line	Performed	B1	N/A	15/01/2019	0.1	Michael Gillett UK.66.47942 2B
5211	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Right hand pilots jettison door handle indication wire replaced IAW AMM 52-11-00, 5-1	Line	Performed	B1	SRP00138 4	06/08/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
5240	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Install service cover to rear structure. (Tail rotor gearbox service covers) IAW AMM 52-40-00, 4-6	Line	Performed	B1	S0009684 4166413	08/02/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
5240	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Forward Access panel removed and fitted IAW AMM 52-40-00, 4-3	Line	Performed	B1	S0011822 4184365	23/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
5240	ZM514 / G-CJXV	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Rear Supply tank cover installed IAW AMM 52-40-00, 4-5	Line	Performed	B1	S0012001 4186084	06/07/2018	0.1	Christopher Bray B1.3 LAE UK.66.498652L
5250	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Gearbox Transmission service cover removed and fitted IAW 52-50-00, 4-2	Line	Performed	B1	S0012324 4188977	28/07/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
5250	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	R/H floor channel access panel removed and fitted IAW 52-50-00, 4-3 S0015061 4215930	Line	Performed	B1	N/A	17/01/2019	0.1	Anthony Mutch UK.66.504133C
5300	G-RIDA	EUROCOPTER	AS 355 NP	Turbomeca Arrius 1	1	Inspection of Spar and attaching screws IAW EASD AS355.05.00.76	Base	Performed	B1	M027993 4142799	15/07/2017	0.3	Mark Young CAA AML/456274G
5300	G-RIDA	EUROCOPTER	AS 355 NP	Turbomeca Arrius 1	1	Check of rear frame reinforcement angles IAW EASB 05.00.62	Base	Performed	B1	M028009 4143542	21/07/2017	0.3	Craig Wilson CAA. AML/ 421889B
5300	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of fuselage for damage, cracks, corrosion IAW AMM 53-50-03, 6-1	Base	Performed	B1	S0011893 4184731	16/08/2018	0.3	Scott Gibbs UK.66.482412A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
5330	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Ensure drain lines from equipment deck and engine deck are clear from obstruction. IAW AMM, 53-30-00, 6-2	Base	Performed	B1	S0010996 4177640	08/06/2018	0.1	Michael Henderson UK.66.47642 1H
5350	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Fin Tip Fairing fitted IAW AMM 53-50-02, 4-1	Base	Performed	B1	S0006886 4148165	15/09/2017	0.1	Christopher Wright B2 LAE UK.66.49216 6F
5350	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	tail rotor drive shaft fairing fitted IAW AMM 53-50-01, 4-1	Line	Performed	B1	S0009684 4166413	08/02/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
5380	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Tail boom removed and Installation IAW AMM 53-80-00-061	Base	Performed	B1	S0008863 4164372	24/01/2018	0.3	Matthew Hynes UK.66.43630 9D
5390	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Tail boom shroud removed and fitted IAW AMM 53-90-00-062	Base	Performed	B1	S0008863 4164372	24/01/2018	0.3	Matthew Hynes UK.66.43630 9D
6210	G-CPAS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Main rotor blades Fitted IAW AMM 62-11-00, 4-2	Base	Performed	B1	S0005999 4122421	27/01/2017	0.1	Kevan Teggart UK.66.46020 7B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6210	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Install Blade tip Fairings IAW AMM 62-10-00-062	Base	Performed	B1	S0008863 4161673 Task 9	26/01/2018	0.6	Matthew Hynes UK.66.436309D
6210	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	PU Tape replaced on Main rotor blade leading edge IAW AMM 62-11-00, 8-4	Base	Performed	B1	S0008536 4168532	27/02/2018	0.3	Becky Smith UK.66.505287D
6210	ZM521 / G-CKIK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor blades (x4) removed for access with mast removal IAW AMM 62-11-00,4-2	Base	Performed	B1	S0009950 4168697	07/03/2018	0.3	Anthony Mutch UK.66.504133C
6210	ZM517 / G-CJZT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of bonding of metal erosion protection on newly installed Main rotor blades carried out IAW AMM 62-11-00,6-1	Line	Performed	B1	s0011405 4180938	12/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.498652L
6230	G-CPAS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Lubrication of Main Swash plate bearing IAW AMM 62-32-00, 3-1	Base	Performed	B1	s0005999	20/01/2017	0.1	Kevan Teggart UK.66.460207B
6230	G-CPAS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	ASB, Swashplate outer clamping ring inspection carried out IAW ASB 135-04A-010	Base	Performed	B1	S0005999	20/01/2017	0.3	Kevan Teggart UK.66.460207B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6230	G-CPAS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Inspection of rotating controls carried out IAW AMM 62-33-00, 6-1	Base	Performed	B1	S0005999 4122421	24/01/2017	0.1	Kevan Teggart UK.66.46020 7B
6230	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Rotor Hub-Shaft torque check carried out IAW AMM 62-31-00, 4-8	Line	Performed	B1	S0009828 4167825	08/03/2018	0.1	Anthony Mutch UK.66.50413 3C
6230	ZM521 / G-CKIK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor Mast fitted IAW AMM 62-31-00, 4-4	Line	Performed	B1	S0009950 4168697	04/04/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
6230	ZM521 / G-CKIK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor hub shaft Disassembled IAW AMM 62-31-00, 4-5	Line	Performed	B1	S0009950 4168697	04/04/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
6230	ZM521 / G-CKIK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor Mast removed IAW AMM 62-31-00, 4-3	Line	Performed	B1	S0009950 4168697	04/04/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
6230	ZM521 / G-CKIK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor hub shaft build up carried out IAW AMM 62-31-00, 4-6	Line	Performed	B1	S0009950 4168697	04/04/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
6230	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of rod end of rotating controls carried out IAW AMM 62-33-00, 6-1	Base	Performed	B1	S0010996 4177640 Task 38	08/06/2018	0.1	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6230	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Rotating Control Rod removed and installed IAW AMM 62-33-00,4-1.	Base	Performed	B1	S0012479	21/08/2018	0.1	Scott Gibbs UK.66.48241 2A
6230	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor hub shaft inspection carried out IAW AMM 62-31-00, 6-3	Base	Performed	B1	S0012479	22/08/2018	0.3	Scott Gibbs UK.66.48241 2A
6240	ZM508 / G-CJRY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	MMI system test carried out IAW AMM 62-44-00, 5-1 post base seal change.	Line	Performed	B1	S0009335 4163435	24/05/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
6300	G-WECG	EUROCOPTER	AS 355 NP	Turbomeca Arrius 1	1	Engine-MGB Coupling Fit IAW AMM 63-06-00-402	Base	Performed	B1	M027640	13/01/2017	0.3	Matthew Hynes UK.66.43630 9D
6300	G-CPAS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Rotor Brake Fluid Change carried out IAW AMM 63-51-00, 3-2	Base	Performed	B1	S000599 4125432	24/01/2017	0.3	Kevan Teggart UK.66.46020 7B
6300	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Rotor brake system inspection carried out IAW AMM 63-51-00, 6-1	Base	Performed	B1	S0010996 4177628	08/06/2018	0.1	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6300	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Bowdenflex Cable Disconnected and reconnected IAW AMM 63-51-00,4-11	Base	Performed	B1	S0012479	21/08/2018	0.1	Scott Gibbs UK.66.48241 2A
6300	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main rotor brake linings replaced IAW AMM 63-51-00,8-1	Base	Performed	B1	S0012479 4193999	22/08/2018	0.1	Scott Gibbs UK.66.48241 2A
6310	ZM519 / G-CKEU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine - Main Gbox Driveshaft removed/fitted IAW AMM 63-11-00, 4-1	Line	Performed	B1	S0012617 4191717	08/08/2018	0.3	Michael Gillet UK.66.47942 2B
6310	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection Post heavy landing Drive Shaft Removed Installed IAW AMM 63-11-00,4-1	Base	Performed	B1	S0012479	21/08/2018	0.4	Scott Gibbs UK.66.48241 2A
6320	G-PSNR	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 C2 Series	Turbomeca Arriel 1	1	Removal Input Shaft IAW AMM 63-11-00, 4-1	Base	Performed	B1	S0006214 4128617	05/05/2017	0.3	Ross Fletcher UK.66.47740 9D
6320	G-PSNR	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 C2 Series	Turbomeca Arriel 1	1	Inspection of Input Shaft carried out IAW AMM 63-11-00,6-1	Base	Performed	B1	S0006214 4128617	05/05/2017	0.3	Ross Fletcher UK.66.47740 9D

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6320	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Gearbox Transmission oil change IAW AMM 63-21-00, 3-1	Line	Performed	B1	S0009758 4167181	09/02/2018	0.1	Andrew Patty UK.66.47246 6F
6320	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main G/Box lower sump cover plate removed and fitted IAW AMM Chap 63-21-00, 4-13	Line	Performed	B1	S0009828 4167825	08/03/2018	0.3	Anthony Mutch UK.66.50413 3C
6320	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	MMI rotating retaining ring removed and fitted to mast IAW AMM 62-31-00, 4-8	Line	Performed	B1	S0009828 4167825	08/03/2018	0.3	Anthony Mutch UK.66.50413 3C
6320	ZM519 / G-CKEU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Gbox - Driveshaft Free Wheel Removed/Fitted IAW AMM 63-21-00, 4-8	Line	Performed	B1	S0012617 4191717	08/08/2018	0.3	Michael Gillet UK.66.47942 2B
6320	ZM519 / G-CKEU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Gbox to Driveshaft input seal replaced IAW AMM 63-21-00, 8-3	Line	Performed	B1	S0012617 4191717	08/08/2018	0.1	Michael Gillet UK.66.47942 2B
6320	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Transmission Removed IAW AMM 63-21-00, 4-1	Base	Performed	B1	S0012479	21/08/2018	0.5	Scott Gibbs UK.66.48241 2A
6320	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Transmission Inspection carried out IAW 63-21-00, 6-1	Base	Performed	B1	S0012479	22/08/2018	0.3	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6320	ZM520 / G-CKEW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Downbird, away from Shawbury MGB OverTorque 88.2% for 0.6 Sec (AEO V<VY) Over torque found to be category D 05-51-10, 6-8 MGB Oil Filter Removed, inspected, and new filter fitted IAW 63-21-00, 4-5 MGB Chip detector checked 63-40-00, 6-1 TGB Chip Detector Checked 65-40-00, 6-1 MRH Shaft Transition area inspected 62-31-0,6-3 MRB Connecting area between cuff and flex beam inspected 62-11-00, 6-1 S0019033	Line	Performed, Supervised, Released	B1	N/A	15/10/2019	0.3	Matthew Clarke UK.66.522890E
6330	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main G/Box Y-strut removed and fitted for access during mast re-torques. 150Hr Checks. IAW AMM 63-31-02, 4-1	Line	Performed	B1	S0009828 4167825 Task°1	08/03/2018	0.4	Anthony Mutch UK.66.504133C
6340	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of chip detector of the main transmission carried out IAW AMM 63-40-00, 6-1	Line	Performed	B1	S0009758 4167181	09/02/2018	0.1	Andrew Patty UK.66.472466F
6340	ZM523 / G-CKJW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Ground run and leak check of MGB number 1 pressure switch post installation, carried out IAW AMM 63-40-00, 8-3	Line	Performed	B1	S0009962 4168733	13/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
6340	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of main gearbox chip detector carried out IAW AMM 63-40-00, 6-1. Chip found of detector and flows charts followed, chip found to be a CAT C.	Base	Performed	B1	S0012711 4192925	18/09/2018	0.3	Michael Gillet UK.66.479422B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6340	ZM525 / C-CKJX	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main G/Box chip caption on start up, Chip inspected IAW AMM 63-40-00, 6-1 and found to be CAT A, Chip refitted AMM 63-40-00,4-1 S0015232 4217274	Line	Performed	B1	N/A	25/01/2019	0.2	Michael Gillett UK.66.47942 2B
6340	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Main Gearbox Chip Cation on power up. Chip Assessed as Category A, chip cleaned IAW 63-40-00, 6-1 S0017756 4243900	Line	Performed, Supervised, Released	B1	N/A	23/07/2019	0.3	Matthew Clarke UK.66.52289 0E
6420	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Dynamic balance weight removed IAW AMM 64-20-00-822	Base	Performed	B1	S0008863 4164372	24/01/2018	0.1	Matthew Hynes UK.66.43630 9D
6500	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the fenestron servo actuator carried out IAW 67-32-00, 6-1	Base	Performed	B1	S0012711 4192925	18/09/2018	0.3	Michael Gillet UK.66.47942 2B
6500	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Rotorbrake pads found worn beyond limits during inspection. Unable to rectify fault due to lack of spares, Fault Transferred to Defered defect log IAW (Dispatch Diviation Manual) MEL for 120 Days Rotor Brake System deactivated IAW MEL. S0017615 4242414	Line	Performed, Supervised, Released	B1/B2	N/A	11/07/2019	0.3	Matthew Clarke UK.66.52289 0E

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6510	ZM532 / G-CKSA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	TRDS removed for access in aid of investigation into NR over speed 118.3 for 2.5 secs. IAW AMM 65-11-00,4-2	Base	Performed	B1	S0009940 4168619	05/03/2018	0.4	Christopher Bray B1.3 LAE UK.66.49865 2L
6510	ZM517 / G-CJZT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Tail rotor drive shaft partially removed and fitted to fit balancing kit IAW AMM 65-11-00, 4-2	Line	Performed	B1	S0009342 4163531	16/03/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
6510	ZM517 / G-CJZT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	TRDS Balancing kit fitted and removed IAW AMM CHP IAW AMM 65-11-00, 5-2.	Line	Performed	B1	S0009342 4163531	16/03/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
6510	ZM517 / G-CJZT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	TRDS Balancing carried out, All Figures found to be within specified parameters. IAW AMM 65-11-00, 5-2.	Line	Performed	B1	S0009342 4163531	16/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
6510	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Forward Drive Shaft Removed / Installed IAW AMM 65-11-00,4-1	Base	Performed	B1	S0012479	21/08/2018	0.1	Scott Gibbs UK.66.48241 2A
6510	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the tail rotor drive shafts carried out IAW AMM 65-11-00, 6-1	Base	Performed	B1	S0012711 4192925	17/09/2018	0.3	Michael Gillet UK.66.47942 2B
6510	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the tail rotor transmission carried out IAW AMM 65-22-00, 6-1	Base	Performed	B1	S0012711 4192925	17/09/2018	0.3	Michael Gillet UK.66.47942 2B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6510	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the tail rotor transmission chip detector carried out IAW 65-40-00, 6-1	Base	Performed	B1	S0012711 4192925	17/09/2018	0.3	Michael Gillet UK.66.47942 2B
6510	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the tail rotor drive shaft carried out IAW 65-11-00, 6-1 S0014514 4211191	Base	Performed	B1	N/A	09/01/2019	0.3	Becky Smith UK.66.50528 7D
6520	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of tail rotor transmission carried out IAW 65-22-00, 6-1 S0014514 4211191	Base	Performed	B1	N/A	09/01/2019	0.1	Becky Smith UK.66.50528 7D
6540	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of the tail rotor transmission chip detector carried out IAW 65-40-00, 6-1	Base	Performed	B1	S0012711 4192925	17/09/2018	0.3	Michael Gillet UK.66.47942 2B
6710	G-CPAO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Roll SEMA replaced IAW AMM 67-10-00 4-10	Base	Performed	B1	S0005368 4122452	26/11/2016	0.3	Daniel Hazell UK.66.47741 3B
6710	G-CPAO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Roll SEMA control rod disassembled and assembled IAW AMM 67-10-00 4-11	Base	Performed	B1	S0005368 4122452	26/11/2016	0.3	Daniel Hazell UK.66.47741 3B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6710	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fault finding, collective lever brake out force found to be excessive during tests. During fault diagnosis, procedure found to be incorrect. Force Trim release will not energise unless aircraft in the power on configuration. Tech query submitted and test passed with new procedure . 67-12-00, 5-1	Base	Performed	B1	S0008536 4155563 °39	06/03/2018	0.3	Christopher Bray B1.3 LAE UK.66.49865 2L
6710	ZM512 / G-CJXS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Yaw and Pitch trim actuators Removed and install for access during ASB EC135H-67A-003 67.14.00,4-1	Base	Performed	B1	s0011234 4179705 2	30/05/2018	0.3	Scott Gibbs UK.66.48241 2A
6710	ZM512 / G-CJXS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Various Trim control rods fitted post ASB IAW AMM 67-14-00, 4-2	Base	Performed	B1	s0011234 4179705 2	30/05/2018	0.3	Scott Gibbs UK.66.48241 2A
6710	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of flying control mixing lever unit components IAW AMM 67-13-00, 6-1	Base	Performed	B1	S0010996 4177640 task 27	08/06/2018	0.1	Scott Gibbs UK.66.48241 2A
6710	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Check torque of collective lever to hinge bearing attachment carried out IAW AMM 67-13-00, 6-1	Base	Performed	B1	S0010996 4177640	08/06/2018	0.1	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6710	ZM509 / G-CJTZ	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Co-pilot collective beep trim, restricted movement in the downward position, during flight conditions, unable to reproduce fault on the ground, Co-pilot collective lever removed from ZM508 and fitted to ZM509 for fault diagnosis. IAW AMM 67-12-00,4-2. Fault fixed with new collective level.	Line	Performed	B1	S001660 4182955	13/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
6710	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Auto pilot functional test carried out IAW AMM 67-14-00 ,5-2	Line	Performed	B1	S0011822 4184365	23/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
6710	ZM529 / G-CKPT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Collective Trim actuator replaced IAW AMM 67-14-00, 4-10	Line	Performed	B1	s0011822 4184365	23/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L
6710	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	inspection of control rods in cabin roof carried out IAW AMM 67-10-00, 61	Base	Performed	B1	S0012711 4192925	18/09/2018	0.3	Michael Gillet UK.66.47942 2B
6720	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Tail Rotor control inspection carried out IAW AMM 67-20-00-221	Base	Performed	B1	S0008863 4165008	24/01/2018	0.1	Matthew Hynes UK.66.43630 9D

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
6720	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Tail rotor series actuator removal and fitted due to corroded hardware IAW AMM 67-20-02-063	Base	Performed	B1	S0008863 4161401	24/01/2018	0.1	Matthew Hynes UK.66.43630 9D
6720	G-NIVA	EUROCOPTER	EC 155 B1	Turbomeca Arriel 2	1	Pilots pedal unit installed IAW AMM 67-20-01-061	Base	Performed	B1	S0008863 4161674	24/01/2018	0.3	Matthew Hynes UK.66.43630 9D
6730	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of fenestron servo actuator carried out IAW 67-32-00, 6-1 S0014514 4211191	Base	Performed	B1	N/A	09/01/2019	0.1	Becky Smith UK.66.50528 7D
7100	G-WECG	EUROCOPTER	AS 355 NP	Turbomeca Arrius 1	1	Engine Fitted IAW AMM 71-06-00-401	Base	Performed	B1	M027640	13/01/2017	0.3	Matthew Hynes UK.66.43630 9D
7100	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Engine Build carried out IAW AMM 71-00-00, 4-14	Base	Performed	B1	S0006857 4136935	12/05/2017	0.3	Mark Young CAA AML/456274 G
7100	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	Engine Installed IAW AMM 71-00-00, 4-2	Base	Performed	B1	S0006857 4136935	12/05/2017	0.3	Mark Young CAA AML/456274 G

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
7100	ZM501 / G-CKGE	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	EDR Installed IAW AMM 71-00-00, 4-5	Base	Performed	B1	S0006857 4136935	12/05/2017	0.3	Mark Young CAA AML/456274 G
7100	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Borescope inspection of centrifugal compressor carried out IAW EMM 71-02-30-280-801	Base	Performed	B1	S0008536 4155562	26/02/2018	0.6	Scott Gibbs UK.66.48241 2A
7100	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Borescope inspection of HP Turbine rear zone carried out IAW EMM 71-02-30-280-804	Base	Performed	B1	S0008536 415564 Item 6	26/02/2018	0.3	Scott Gibbs UK.66.48241 2A
7100	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Borescopic inspection of the HP Turbine front zone IAW EMM 71-02-30-280-803	Base	Performed	B1	S0008536 4155565	01/03/2018	0.3	Scott Gibbs UK.66.48241 2A
7100	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine rinse carried out IAW EMM 71-01-01-610-801	Line	Performed	B1	S0010033 4169313	15/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
7100	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine clean carried out IAW EMM 71-01-03-610-801	Line	Performed	B1	S0010033 4169313	15/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
7100	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine power check carried out IAW EMM 71-02-13-280-801-A01	Line	Performed	B1	S001003 4169313	15/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
7100	ZM519 / G-CKEU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine placed into type 1 storage IAW EMM 71-05-01-550-801-A01	Line	Performed	B1	S0011099 4178390	10/05/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
7100	ZM508 / G-CJRY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine Wash and engine power check carried out IAW EMM 71-01-03-610-801 S0016968 4235524	Line	Performed	B1	N/A	24/06/2019	0.3	Christopher Bray B1.3 LAE UK.66.498652L
7100	ZM514 / G-CJXV	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	No 2 Engine Replacement due to continuous leaking from output seal IAW 71-00-00, 4-1 Post Engine Change ground runs and flight test carried out IAW 05-60-00, 6-6 S0022102	Line	Performed, Supervised, Released	B1	N/A	10/06/2020	3	Matthew Clarke UK.66.522890E
7111	G-TVHB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Engine Cowlings and transmission fairings inspection carried out IAW AMM 71-11-00, 6-1	Base	Performed	B1	S0007290 4141898	04/08/2017	0.3	Neven Donaldson UK.66.491994G
7111	ZM502 - G-CJRW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	MBB-BK 117 D2 Series	Turbomeca Arriel 2	1	LH and RH engine cowling installed IAW AMM 71-11-00, 4-1	Line	Performed	B1	S0009694 4166722	08/02/2018	0.1	Christopher Bray B1.3 LAE UK.66.498652L
7111	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	LH and RH Transmission Fairings removed and installed IAW AMM 71-11-00,4-4	Line	Performed	B1	S0009684 4166413	08/02/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
7111	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Aft LH Engine Cowlings installed IAW AMM 71-11-00,4-3	Line	Performed	B1	S0009684 4166413	08/02/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
7111	ZM522 / G-CKIM	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Remove transmission fairings from both sides IAW AMM 71-11-00, 4-4	Base	Performed	B1	S0009758 4167181	09/02/2018	0.1	Andrew Patty UK.66.47246 6F
7121	G-CPAO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Engine Mount Bearing Changed IAW AMM 71-21-00, 8-2	Base	Performed	B1	S0005368 4121818	18/11/2016	0.3	Daniel Hazell UK.66.47741 3B
7121	G-CPAO	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Engine Alignment carried out IAW AMM 71-00-00, 5-1	Base	Performed	B1	S0005368 4121818	18/11/2016	0.3	Daniel Hazell UK.66.47741 3B
7121	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine Indication system - Pyrometric harness, Removal and Installation IAW EMM 77-21-00-900-801-B01	Line	Performed	B1	S0012378 4189320	03/08/2018	0.3	Michael Gillet UK.66.47942 2B
7130	G-CPAS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Firewalls inspected IAW AMM 71-32-00, 6-1	Base	Performed	B1	S0005999 4125418	23/02/2017	0.3	Kevan Teggart UK.66.46020 7B

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
7200	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	FADEC 2 Signal Fail on ground run whilst exercising FADECS using torque trim +/- 15%, Engine torque conformation box functionally tested IAW Engine maintenance manual Chap 72-11-00-750-801-A01, No Fault found	Line	Performed	B1	S0013243 4198210	18/09/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
7300	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Introduction of injector seals carried out IAW ASB 319-73-2142	Line	Performed	B1	S0012378 4189320	03/08/2018	0.3	Michael Gillet UK.66.47942 2B
7310	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Fuel system - Adjusted Valve/Assembly, Removal and Installallation IAW EMM 73-14-00-900-801-C01	Line	Performed	B1	S0012378 4189320	03/08/2018	0.1	Michael Gillet UK.66.47942 2B
7310	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Injector Manifold and preference injector pipes Removed and installed IAW EMM 73-15-00-900-801-B01	Line	Performed	B1	S0012378 4189320	03/08/2018	0.3	Michael Gillet UK.66.47942 2B
7320	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Install LH HMU Post inspection, IAW EMM 73-23-00-900-801-D01	Base	Performed	B1	S0008536 4155558	28/02/2018	0.5	Scott Gibbs UK.66.48241 2A
7320	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Functional test of Emergency engine control carried out IAW AMM 76-12-00, 5-2	Base	Performed	B1	S0008536 4155558	28/02/2018	0.5	Scott Gibbs UK.66.48241 2A

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
7321	ZM510 / G-CJUA	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	EECU Download for OEI Overlimit IAW EMM73-21-00-280-807-A01	Line	Performed	B1	S0009859 4167995	21/02/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
7321	ZM516 / G-CJZS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	FADEC 2 Signal Fail on ground run whilst exercising FADECS using torque trim +/- 15%, R/H and L/H Torque conformation unit box?s transposed IAW engine maintenance manual Chap 73-21-00-900-801-A01	Line	Performed	B1	S0013243 4198210	18/09/2018	0.3	Adam Keenaghan B1.3 LAE IE.66.273270
7421	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Igniter removed for access IAW EMM 74-21-10-900-802	Base	Performed	B1	S0008536 4155565	01/03/2018	0.3	Scott Gibbs UK.66.48241 2A
7421	ZM505 / G-CJIW	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Igniter plugs fitted post boroscope inspections. IAW EMM 74-21-10-900-802-B01	Base	Performed	B1	S0008536 4155564 Task°8	07/03/2018	0.4	Anthony Mutch UK.66.50413 3C
7610	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	inspection of the power controls carried out IAW AMM 76-10-00, 6-1	Base	Performed	B1	S0012711 4192925	18/09/2018	0.3	Michael Gillet UK.66.47942 2B
7700	G-SUFK	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Engine Indication inspection carried out IAW AMM 77-00-00, 6-1	Base	Performed	B1	S0006886	15/09/2017	0.1	Christopher Wright B2 LAE UK.66.49216 6F

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
7721	G-CPAS	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 P2 Series	PWC PW206	1	Sensor and trim unit inspection/Check IAW EMM 77-21-00	Base	Performed	B1	S000599 4125447	24/01/2017	0.3	Kevan Teggart UK.66.46020 7B
7920	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	AFT Air Duct - Air Ducts and Oil Cooler removed and installed for main gearbox removal 79-22-00, 4-3	Base	Performed	B1	S0012479	21/08/2018	0.1	Scott Gibbs UK.66.48241 2A
7920	ZM531 / G-CKSB	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection and functional test of engine fuzz burners carried out IAW AMM 79-24-00, 6-1 s0014514 4211190	Base	Performed	B1	N/A	08/01/2019	0.1	Becky Smith UK.66.50528 7D
7921	ZM506 / G-CJIY	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Engine oil Distribution Removed and installed for Main gearbox removed IAW 79-21-00, 4-1	Base	Performed	B1	S0012479	21/08/2018	0.1	Scott Gibbs UK.66.48241 2A
7921	ZM504 / G-CJJG	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Inspection of engine fuzz burners carried out IAW AMM 79-24-00, 6-1	Base	Performed	B1	S0012711 4192924	18/09/2018	0.1	Michael Henderson UK.66.47642 1H
7930	ZM517 / G-CJZT	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	Magnetic engine plug cleaned IAW EMM 79-38-00-110-801	Line	Performed	B1	S0011405 4180945	12/06/2018	0.1	Christopher Bray B1.3 LAE UK.66.49865 2L

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

ATA	Reg	Manufacturer	Model	Engine	Group	Task Details	Maint	Activity	Cat	J.W.L. Nr	Date	Days	Supervisor
8530	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	MX10 camera system removed from Aircraft IAW AMM 85-32-10 4-1	Line	Performed	B1	00010149 4170361	13/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
8530	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	MX10 hand controller removed IAW SAMM 85-32-10 4-2	Line	Performed	B1	00010149 4170361	13/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270
8530	ZM513 / G-CJXU	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	EC135 T3H	Turbomeca Arrius 2B	1	MX10 digital recorder removed IAW SAMM 85-32-10 4-3	Line	Performed	B1	00010149 4170361	13/03/2018	0.1	Adam Keenaghan B1.3 LAE IE.66.273270

Matthew Clarke
matclarke216@hotmail.co.uk
07894120889

Recent Experience Report

Time Period: From 18/11/2016 to 21/08/2020

EASA License Nr: *UK.66.522890E*
EASA Expiry date: *12/05/2024*

Filter(s): No Filters

Status Report

Group	Category	Absolute Total	Total (in report)	Total Hour(s) (last 2 years)	Total Day(s) (last 2 years)
1	B1	53 Days	53 Days	0 Hours	0 Days
1	B1/B2	2 Days	2 Days	0 Hours	0 Days
2b	B1	1 Day	1 Day	0 Hours	0 Days

I hereby certify that all information given on this report is true and correct.

Date