



Aviation Investigation Final Report

Location: Moab, Utah **Accident Number:** GAA18CA477

Date & Time: May 19, 2018, 10:00 Local Registration: N833RD

Aircraft: Davidson, Ronald A. Avid Aircraft Damage: Substantial

Defining Event: Nose over/nose down **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot in the tailwheel-equipped airplane reported that, during the landing roll on the dirt surface, he "pinned" the tailwheel on the ground and that he then applied aft stick to keep the tailwheel on the ground. However, he was concerned about the condition of the last third of the runway, and he chose to stop before it. He reported that he applied the brakes "a little harder than normal" and that the tail rose off the ground. He released his brake application, but the tail continued to rise, and the airplane nosed over.

The airplane sustained substantial damage to the vertical stabilizer and the rudder.

The pilot reported that there was still had about 1,000 ft of runway remaining but that he failed to recognize and correct for the momentum of the rising tail in a timely manner.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's excessive brake application and delayed remedial action, which resulted in a nose-over.

Findings

Aircraft Brake - Incorrect use/operation

Personnel issues Use of equip/system - Pilot

Personnel issues Delayed action - Pilot

Personnel issues Identification/recognition - Pilot

Page 2 of 5 GAA18CA477

Factual Information

History of Flight

Landing-landing roll	Miscellaneous/other	
Landing-landing roll	Nose over/nose down (Defining event)	

Pilot Information

Certificate:	Commercial	Age:	44,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	July 1, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 9, 2016
Flight Time:	(Estimated) 1195.1 hours (Total, all aircraft), 87.6 hours (Total, this make and model), 926.9 hours (Pilot In Command, all aircraft), 21.3 hours (Last 90 days, all aircraft), 12.6 hours (Last 30 days, all aircraft), 8.6 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

•			
Aircraft Make:	Davidson, Ronald A.	Registration:	N833RD
Model/Series:	Avid Magnum	Aircraft Category:	Airplane
Year of Manufacture:	2017	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	M76
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	April 12, 2018 Condition	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	217.1 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-360
Registered Owner:		Rated Power:	200 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA477

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCNY,4560 ft msl	Distance from Accident Site:	17 Nautical Miles
Observation Time:	15:53 Local	Direction from Accident Site:	38°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.95 inches Hg	Temperature/Dew Point:	19°C / 2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Moab, UT (KCNY)	Type of Flight Plan Filed:	None
Destination:	Moab, UT (UT75)	Type of Clearance:	None
Departure Time:	09:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	Mineral Canyon Strip UT75	Runway Surface Type:	Dirt
Airport Elevation:	3900 ft msl	Runway Surface Condition:	Dry
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	2000 ft / 40 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	38.533332,-109.983329(est)

Page 4 of 5 GAA18CA477

Administrative Information

Investigator In Charge (IIC): Hicks, Michael

Additional Participating Persons: Kent Gibbons; FAA; Salt Lake City, UT

Original Publish Date: June 10, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=98019

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA18CA477