



Aviation Investigation Final Report

Location: Guttenberg, Iowa Accident Number: GAA17CA317

Date & Time: June 3, 2017, 14:00 Local Registration: N34462

Aircraft: Cessna 177 Aircraft Damage: Substantial

Defining Event: Miscellaneous/other **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, during final, "all seemed normal until [he] felt the plane drop." He added that he heard the stall warning horn chirp and added full power "[too] late." The left wing sheared off after impacting a street sign, and the airplane came to rest on the left side of the runway.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

A review of recorded data from the automated weather observation station located about 12 miles north of the accident airport revealed that, about the time of the accident, the wind was from 210° at 9 knots. The airplane was landing on runway 17.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain an adequate approach path, which resulted in the left wing impacting a street sign.

Findings

Aircraft Descent/approach/glide path - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Sign/marker - Effect on equipment

Page 2 of 5 GAA17CA317

Factual Information

History of Flight

Approach-VFR pattern final	inal Miscellaneous/other (Defining event)	
Approach-VFR pattern final	Attempted remediation/recovery	
Approach-VFR pattern final	Collision with terr/obj (non-CFIT)	

Pilot Information

Certificate:	Private	Age:	61,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	November 23, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N34462
Model/Series:	177 B	Aircraft Category:	Airplane
Year of Manufacture:	1972	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17701819
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	January 24, 2017 Annual	Certified Max Gross Wt.:	2500 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	5769.6 Hrs as of last inspection	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-360-A1F6D
Registered Owner:		Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA17CA317

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KPDC,661 ft msl	Distance from Accident Site:	12 Nautical Miles
Observation Time:	18:55 Local	Direction from Accident Site:	355°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.92 inches Hg	Temperature/Dew Point:	32°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	DAVENPORT, IA (DVN)	Type of Flight Plan Filed:	None
Destination:	Guttenberg, IA (IA23)	Type of Clearance:	None
Departure Time:	15:15 Local	Type of Airspace:	Class G

Airport Information

Airport:	GAA PRIVATE IA23	Runway Surface Type:	Grass/turf
Airport Elevation:	620 ft msl	Runway Surface Condition:	Dry;Vegetation
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	2540 ft / 160 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.8125,-91.098892(est)

Page 4 of 5 GAA17CA317

Administrative Information

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Dan Michaelsen; FAA; Des Moines, IA

Original Publish Date: August 3, 2017

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=95293

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA17CA317