



Aviation Investigation Final Report

Location: Malin, Oregon

Date & Time: June 27, 2018, 07:47 Local

Aircraft: GRUMMAN ACFT ENG COR-SCHWEIZER G 164

Defining Event: Aerodynamic stall/spin

Flight Conducted Under: Part 137: Agricultural

Accident Number: GAA18CA383

Registration: N151QC

Aircraft Damage: Substantial

Injuries: 1 None

Analysis

The pilot reported that, during an agricultural application flight, he misjudged the approach and did not have enough clearance to avoid power lines. The airplane began to sink, and he pulled back on the flight control stick. Subsequently, the airplane aerodynamically stalled and then struck power lines.

The airplane sustained substantial damage to the fuselage, empennage, and both wings.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's misjudgment of the approach and his subsequent exceedance of the airplane's critical angle of attack during an agricultural application flight, which resulted in an aerodynamic stall and collision with power lines.

Findings

Aircraft Angle of attack - Capability exceeded

Personnel issues Aircraft control - Pilot

Personnel issues Monitoring environment - Pilot

Environmental issues Wire - Effect on operation

Page 2 of 5 GAA18CA383

Factual Information

History of Flight

Maneuvering-low-alt flying	Miscellaneous/other
Maneuvering-low-alt flying	Aerodynamic stall/spin (Defining event)
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT)

Pilot Information

			00.14
Certificate:	Commercial	Age:	29,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	January 30, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 11, 2017
Flight Time:	(Estimated) 3625 hours (Total, all aircraft), 2520 hours (Total, this make and model), 3575 hours (Pilot In Command, all aircraft), 320 hours (Last 90 days, all aircraft), 150 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA18CA383

Aircraft and Owner/Operator Information

Aircraft Make:	GRUMMAN ACFT ENG COR- SCHWEIZER	Registration:	N151QC
Model/Series:	G 164 B	Aircraft Category:	Airplane
Year of Manufacture:	1978	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	474B
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 1, 2018 Annual	Certified Max Gross Wt.:	5200 lbs
Time Since Last Inspection:		Engines:	1 Turbo prop
Airframe Total Time:	4221.5 Hrs as of last inspection	Engine Manufacturer:	Honeywell
ELT:	Not installed	Engine Model/Series:	TPE331-2-201A
Registered Owner:		Rated Power:	715 Horsepower
Operator:		Operating Certificate(s) Held:	Agricultural aircraft (137)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KLMT,4092 ft msl	Distance from Accident Site:	2 Nautical Miles
Observation Time:	14:53 Local	Direction from Accident Site:	321°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.03 inches Hg	Temperature/Dew Point:	16°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Tulelake, CA (O81)	Type of Flight Plan Filed:	None
Destination:	Tulelake, CA (O81)	Type of Clearance:	None
Departure Time:	07:47 Local	Type of Airspace:	Class G

Page 4 of 5 GAA18CA383

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.11972,-121.694168(est)

Administrative Information

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Rich Davis; FAA; Portland, OR

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=97621

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA383