



Aviation Investigation Final Report

Location: Cedar Rapids, Iowa Accident Number: GAA18CA156

Date & Time: March 11, 2018, 14:25 Local Registration: N9457K

Aircraft: Stinson 108 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, during a three-point landing, the tailwheel touched down first, and as the main landing gear touched down the airplane bounced. He applied more back pressure on the yoke, and as the airplane settled on the main landing gear it veered to the left. He applied right rudder and brake to no avail. Subsequently, the right wingtip struck the ground, and the airplane nosed over.

The airplane sustained substantial damage to the left wing, the right-wing lift strut, and the empennage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The automated weather observation system located at the accident airport reported that, about the time of the accident, the wind was from 010° at 6 knots. The pilot landed on runway 9.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare, which resulted in a loss of directional control and a nose-over.

Findings

Aircraft Landing flare - Not attained/maintained

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 5 GAA18CA156

Factual Information

History of Flight

Landing	Loss of control on ground (Defining event)	
Landing	Attempted remediation/recovery	
Landing	Nose over/nose down	
Landing	Abnormal runway contact	
Landing	Abhornar unway contact	

Pilot Information

Certificate:	Commercial	Age:	58,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	March 23, 2017
Occupational Pilot:	No	Last Flight Review or Equivalent:	August 25, 2016
Flight Time:	(Estimated) 764 hours (Total, all aircraft), 324 hours (Total, this make and model), 641 hours (Pilot In Command, all aircraft), 2 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Stinson	Registration:	N9457K
Model/Series:	108 2	Aircraft Category:	Airplane
Year of Manufacture:	1947	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	108-2457
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	November 27, 2017 Annual	Certified Max Gross Wt.:	2230 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2238 Hrs at time of accident	Engine Manufacturer:	FRANKLIN
ELT:	C91 installed, not activated	Engine Model/Series:	6A4-165-B3
Registered Owner:		Rated Power:	165 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA156

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCID,868 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	19:52 Local	Direction from Accident Site:	246°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 4600 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.2 inches Hg	Temperature/Dew Point:	7°C / -7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Cedar Rapids, IA (CID)	Type of Flight Plan Filed:	None
Destination:	Cedar Rapids, IA (CID)	Type of Clearance:	VFR
Departure Time:	14:00 Local	Type of Airspace:	Class C

Airport Information

Airport:	THE EASTERN IOWA CID	Runway Surface Type:	Concrete
Airport Elevation:	869 ft msl	Runway Surface Condition:	Dry
Runway Used:	09	IFR Approach:	None
Runway Length/Width:	8600 ft / 150 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	41.88639,-91.706947(est)

Page 4 of 5 GAA18CA156

Administrative Information

Investigator In Charge (IIC): Swenson, Eric

Additional Participating Persons: Brett Hoben; FAA; Ankeny, IA

Original Publish Date: June 14, 2018

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=96855

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA18CA156