

# **Aviation Investigation Final Report**

Location: Merritt Island, Florida Accident Number: GAA18CA479

Date & Time: August 9, 2018, 10:00 Local Registration: N487JK

Aircraft: Piper PA28 Aircraft Damage: Substantial

**Defining Event:** Aerodynamic stall/spin **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

#### **Analysis**

The solo student pilot reported that, during landing, before initiating the landing flare, he saw a "white bird" heading toward the airplane. He applied left rudder to avoid the bird, and the airplane drifted left of the runway centerline. He then "[pulled] the yoke back," but the left main landing gear impacted a taxiway sign, and the airplane settled on grass adjacent to the runway.

The airplane sustained substantial damage to the left-wing spar.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's exceedance of the airplane's critical angle of attack while maneuvering to avoid a bird during the landing flare, which resulted in an aerodynamic stall.

# **Findings**

Aircraft Angle of attack - Capability exceeded

Personnel issues Aircraft control - Pilot

 $\textbf{Environmental issues} \hspace{1.5cm} \textbf{Animal(s)/bird(s) - Effect on operation}$ 

Page 2 of 5 GAA18CA479

# **Factual Information**

# **History of Flight**

Landing-flare/touchdown	Abrupt maneuver	
Landing-flare/touchdown	Aerodynamic stall/spin (Defining event)	
Landing-flare/touchdown	Loss of control in flight	
Landing-flare/touchdown	Collision with terr/obj (non-CFIT)	

# **Student pilot Information**

Certificate:	Student	Age:	18,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	July 11, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 21 hours (Total, all aircraft), 21 hours (Total, this make and model), 2 hours (Pilot In Command, all aircraft), 21 hours (Last 90 days, all aircraft), 18 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA18CA479

### Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N487JK
Model/Series:	PA28 161	Aircraft Category:	Airplane
Year of Manufacture:	1998	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	2842044
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	July 3, 2018 100 hour	Certified Max Gross Wt.:	2447 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	10899.2 Hrs	Engine Manufacturer:	Lycoming
ELT:	C91A installed, not activated	Engine Model/Series:	0-320-D3G
Registered Owner:		Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	Pilot school (141)

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCOF,8 ft msl	Distance from Accident Site:	8 Nautical Miles
Observation Time:	13:56 Local	Direction from Accident Site:	145°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.11 inches Hg	Temperature/Dew Point:	30°C / 24°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Merritt Island, FL (COI)	Type of Flight Plan Filed:	None
Destination:	Merritt Island, FL (COI)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 4 of 5 GAA18CA479

#### **Airport Information**

Airport:	MERRITT ISLAND COI	Runway Surface Type:	Asphalt
Airport Elevation:	5 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	29	IFR Approach:	None
Runway Length/Width:	3601 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

#### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	28.341667,-80.686943(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Nepomuceno, Eleazar
Additional Participating Persons:	Scott Strickland; FAA; Orlando, FL
Original Publish Date:	November 6, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98033

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA479